

INSPECTION REPORT



End of contract

GENERAL INFO

File	315800
License plate	1XSW492
Vehicle identification number	WVGZZZ1TZLW040975
Dossier	2019332237
Make	Volkswagen Touran 2.0TDi 150 H
Mileage	156377
First registration	11/05/2020
client availability date	29/06/2026
inspectionDate	11/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
33	Front Bonnet // Repair & Painting	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
89	Door Front Left / Window / Replace	Y
92	Rocker Panel Left // Painting	Y
100	Door Rear Left // Smart Repair Small	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
150	Rear Bonnet // Smart Repair Small	Y
152	Rear Bonnet // Smart Repair Large	Y
181	Wing Rear Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
219	Door Front Right / Window / Replace	N
341	Wheel Alloy Front Right // Repair	N
565	Dashboard / Storage Tray / Replace	N
568	Dashboard / Ventilation Outlet / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
615	Front Left Door Interior Coating / Reflector / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Front Left / Window / Replace-scratch



Door Rear Left // Smart Repair Small-scratch



Bumper Rear // Polish-scratch



Door Front Right / Window / Replace-scratch



Door Front Right // Smart Repair Small-scratch



Wheel Alloy Front Right // Repair-scratch



Bumper Front // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Side View Mirror Left // Painting-scratch



Door Front Left / Trim / Replace-scratch



Rocker Panel Left // Painting-scratch




Wing Rear Left // Polish-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Front Left Door Interior Coating // Replace Completely-scratch




Dashboard / Steering Wheel / Replace-scratch



Wing Rear Right // Smart Repair Medium-dent



Rear Bonnet // Smart Repair Small-dent



Front Bonnet // Repair & Painting-scratch + dent



Dashboard / Ventilation Outlet / Replace-cracked



Front Left Door Interior Coating / Reflector / Replace-missing



Rear Bonnet // Smart Repair Large-Chemical reaction



Interior Cleaning // Small-stain



