

DEKRA Automotive Solutions

Vehicle details

VIN	VNVF40007 73081287	Mileage	34 822 km	Engine (Fuel) Type	Diesel
Licence Plate	CB9446	Registration date	17/06/2024	Engine size	1997
Brand	NISSAN	Fuel level	-	Transmission	Manual
Model	Primastar-2006	Car type	LCV	Gears	-
Body Type	Saloon / Hatchback	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Blanc		

Inspection Details

Inspection date	19/06/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique
-----------------	------------	-----------------	---------------------------	-------------	------------------------




Other technical information



Manual air-conditioning	Spare wheel (wheel & tyre)	✓	Service manual holder	✓
Cruise control	Triangle	✓	User manual	✓
Rain and light sensor	Jack	✓	Warranty booklet	✓
Anti-fog lights	Safety vest	✓	First aid kit	✓
Reversing radars	Fire extinguisher	✓	Adapter USB	✓
			Key	✓

Options / Equipment






Tyres



Damages

1		Part	Door	2		Part	Unpainted bumper
		Position	Back right			Position	Back right
		Damages	Dented			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Replace

DEKRA Automotive Solutions

<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Unpainted bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Unpainted bumper	Position	Back	Damages	Scratched	Severity	-	Repair mode	For info	<p>4</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Fabric seat</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Fabric seat	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Unpainted bumper																						
Position	Back																						
Damages	Scratched																						
Severity	-																						
Repair mode	For info																						
Part	Fabric seat																						
Position	Front																						
Damages	Stained/dirty																						
Severity	-																						
Repair mode	Cleaning																						
<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Wheelcap 16"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Wheelcap 16"	Position	Front right	Damages	Missing	Severity	-	Repair mode	Replace	<p>6</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scratched	Severity	-	Repair mode	Smart Repair
Part	Wheelcap 16"																						
Position	Front right																						
Damages	Missing																						
Severity	-																						
Repair mode	Replace																						
Part	Bumper																						
Position	Front																						
Damages	Scratched																						
Severity	-																						
Repair mode	Smart Repair																						
<p>7</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Lower bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Lower bumper	Position	Front	Damages	Dented	Severity	-	Repair mode	Replace												
Part	Lower bumper																						
Position	Front																						
Damages	Dented																						
Severity	-																						
Repair mode	Replace																						