MACADAM








RENAULT EXPRESS: 3809-MSK

Vinnumber:	**VF1RJK00472091190**	Versionname:	**Advance 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual**
First Registrationdate:	**25/06/2024**	Fiscalpower:	
Expertise Mileage:	**127470**	Power Kw:	
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**No**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**		
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**185/65/15/86 H**			
	Fr.L.	**Goodyear: 5 mm**	Fr.R.	**Goodyear: 5 mm**
	Re.L.	**Goodyear: 5 mm**	Re.R.	**Goodyear: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**185/65 R 15 86 H**
Tyre size FR	**185/65 R 15 86 H**
Tyre size RL	**185/65 R 15 86 H**
Tyre size RR	**185/65 R 15 86 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Service book, Missing, Repair/replace (lump sum)




User's manual, Missing, Repair/replace (lump sum)




MOT certificate, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)




Floor covering FL, Tear, Replace




Steering wheel, Worn, Replace




Malfunction indicator, Blinking, Check




Door FL, Dent(s), Repair and paint (complete)




Bumper F, Scratch(es), Paint





Number plate F, Deformed / Strained, Repair/replace (lump sum)




Rear light R, Crack, Replace




Wing RR, Dent(s), Repair and paint (complete)




Sliding door R, Dent(s), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Paint




Rear panel, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Paint




Tyres, No damage, Check










ALPHABET

Datos del vehículo

Marca	RENAULT	Matrícula	3809-MSK
Modelo	Express	VIN	VF1RJK00472091190
Versión	Advance 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
19/06/2025	Luna parabrisas	0	RALARSA HOLDING S.L.
20/11/2025	Paragolpes delantero	0	Renaul Jerez Frontera Caetano Formula Cadiz
11/11/2024	Pinchazo+Equilibrado, Sustitución	30856	INDUSTRIAL TYRE 2017, S.L
15/11/2024	Rev. 30.000 kms	33215	CAETANO FORMULA CADIZ S.L.
07/02/2025	Pastillas delanteras	48193	NEUMATICOS SOLEDAD S.L.
14/03/2025	Pastillas delanteras, Rev. 60.000 kms	64670	CAETANO FORMULA CADIZ S.L.
02/06/2025	Retrovisor izquierdo Completo, Aleta delantera izquierda	73242	TALLER DE CHAPA Y PINTURA MUÑOZ
23/04/2025	Faros, Paragolpes delantero, Aleta delantera derecha, Puerta delantera derecha	73242	TALLER DE CHAPA Y PINTURA MUÑOZ
22/07/2025	Ecotasa - N2, Goodyear / 542242 185/65X15 GYEAR.EFIG.PERF2 88H, Sustitucion y kit de montaje	82424	INDUSTRIAL TYRE 2017 S.L.
22/01/2026	Aceite motor - - - APL 12, Filtro aceite, Filtro antipolen - Nueva, Másticos, Rellenar niveles, Serv inspección 60000 KM, Sustituir Másticos, Sustituir Rellenar niveles, Sustituir Serv inspección 60000 KM, Tasa de gestión de aceites usados, Verificar Diagnosis	97140	CAETANO FORMULA CADIZ, S.L.U - LOS BARRIOS
04/06/2026	Ecotasa - N2, Goodyear / 542242 185/65X15 GYEAR.EFIG.PERF2 88H, Sustitucion y kit de montaje	118906	INDUSTRIAL TYRE 2017 S.L.
10/07/2026	Fluido refrigerante a/c, Sustituir Fluido refrigerante a/c, Verificar Diagnosis	118938	CAETANO FORMULA CADIZ, S.L.U - JEREZ DE LA FRONTERA

Fecha	Descripción	Kilómetros	Taller
17/09/2026	Aceite motor - - - ALP EURO, Filtro aceite, Filtro antipolen, Importe de pago por uso, Líquido frenos - DOT4 OEM, Prueba funcional, Serv inspección 2º año, Servicio de inspección técnica, Sustituir Filtro antipolen, Sustituir Líquido frenos, Sustituir Prueba funcional, Sustituir Servicio de inspección técnica, Sustituir Traslado, Tasa de gestión de aceites usados, Traslado	130700	Mario Guillen Hormigo