MACADAM








CITROËN Berlingo: 0409-NFS

Vinnumber:	**VR7EDYHT6SJ651053**	Versionname:	**Citroen Talla M BlueHDi 100 furgón derivado de turismo 75kW 4P manual**
First Registrationdate:	**3/09/2025**	Fiscalpower:	
Expertise Mileage:	**62190**	Power Kw:	
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Tow bar	
Number keys remote	**2**	Radio	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**195/65/15/95 H**			
	Fr.L.	**Fulda: 6 mm**	Fr.R.	**Fulda: 6 mm**
	Re.L.	**Fulda: 7 mm**	Re.R.	**Fulda: 7 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**195/65 R 15 95 H**
Tyre size FR	**195/65 R 15 95 H**
Tyre size RL	**195/65 R 15 95 H**
Tyre size RR	**195/65 R 15 95 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**2484**
Tyre make FR	**2484**
Tyre make RL	**2484**
Tyre make RR	**2484**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Interior, Dirty, Cleaning



Boot lid covering R, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Rear light L, Waterinfiltration, Replace



Windscreen, Broken, Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Bumper F, Scratch(es), Paint



Outside rear-view mirror housing R, Scratch(es), Acceptable



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Internal boot lining L, Scratch(es), Replace



Internal boot lining L, Scratch(es), Replace




Internal boot lining R, Scratch(es), Replace




Tyres, No damage, Check






ALPHABET

Datos del vehículo

Marca	CITROËN	Matrícula	0409-NFS
Modelo	Berlingo	VIN	VR7EDYHT6SJ651053
Versión	Citroen Talla M BlueHDi 100 furgón derivado de turismo 75kW 4P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
03/02/2026	Aceite motor - 05W30, Arandela / tapón cárter, Filtro aceite - Nueva, Filtro aire - MECAFILTER - LAUTRETTE - Rec.Plat. GIRA - Nueva, Filtro antipolen - Nueva, Filtro combustible - Nueva, Líquido lavaparabrisas - -20ºC - Nueva, Másticos, Serv inspección 30000 KM, Sustituir Filtro aire, Sustituir Filtro antipolen, Sustituir Filtro combustible, Sustituir Másticos, Tasa de gestión de aceites usados	21300	NAMOVIL 2003 S.L.
04/02/2026	Alineado sencillo, Ecotasa - N2, Fulda / 542563 195/65X15 FULDA ECOCNTRHP2 95H, Sustitucion y kit de montaje	21310	NAMOVIL 2003 S.L.
16/03/2026	Ecotasa - N2, Goodyear / 547256 195/65X15 GYEAR.EFIG.PERF2 95H, Sustitucion y kit de montaje	29412	NEUMÁTICOS SOLEDAD (VALLADOLID - ARGALES)
17/04/2026	Luna parabrisas	35622	RALARSA HOLDING S.L.
09/07/2026	Aceite motor - 05W30, Arandela / tapón cárter, Filtro aceite - Nueva, Filtro aire - Nueva, Filtro antipolen - Nueva, Filtro combustible - Nueva, Líquido lavaparabrisas, Másticos, Serv inspección 60000 KM, Sustituir Filtro aire, Sustituir Filtro antipolen, Sustituir Filtro combustible, Sustituir Másticos, Tasa de gestión de aceites usados | Alineado sencillo, Cooper / 726182 - 195/65R15 95H COOPER SUMMER XL, Ecotasa - N2, Sustitucion y kit de montaje	53270	NAMOVIL 2003 S.L.

Fecha	Descripción	Kilómetros	Taller