MACADAM








BMW 1 Reeks (UKL): 2CNF425

Vinnumber:	**WBA7K110205V68294**	Versionname:	**116i (F40) 1.5i 109pk/cv 5p**
First Registrationdate:	**26/09/2022**	Fiscalpower:	
Expertise Mileage:	**84007**	Power Kw:	**80**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/91 W**			
	Fr.L.	**Bridgestone: 5 mm**	Fr.R.	**Bridgestone: 5 mm**
	Re.L.	**Bridgestone: 5 mm**	Re.R.	**Bridgestone: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**205/55 R 16 91 W**
Tyre size FR	**205/55 R 16 91 W**
Tyre size RL	**205/55 R 16 91 W**
Tyre size RR	**205/55 R 16 91 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Windscreen, Scratch(es), Replace







Bumper F, Scratch(es), Repair and paint (complete)









Bumper moulding F, Scratch(es), Replace




Alloy rim FL, Scratch(es), Repair and paint (complete)






Door FL, Scratch(es), Acceptable





Door RL, Chemical polution, Polish




Door RL, Chemical polution, Polish





Boot lid covering R, Scratch(es), Acceptable




Luggage compartment cover, Broken, Forfeit




Bumper R, Deformed / Strained, Replace and paint








Tailgate / Boot, Deformed / Strained, Replace and paint






Wheel aperture RR, Scratch(es), Acceptable




Alloy rim RR, Scratch(es), Repair and paint (complete)





Wing RR, Scratch(es), Spot repair





Sill trim R, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Repair and paint (complete)




Bodywork, Paint measurement, Acceptable



Bodywork, Not original part, Remove lettering






Bodywork, Accident, Check



Roof, Chemical polution, Repair and paint (complete)
















Onderhoudshistorie van: WBA7K110205V68294

ALPHABET

Kenteken	2CNF425
Merk Model	BMW 116i (F40) 1.5i 109pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	9/26/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/11/26	82,199	BMW/MINI service standaard omvang	Uitvoeren
6/11/26	82,199	klein materiaal	
6/11/26	82,199	service microfilter	Uitvoeren
6/11/26	82,199	service motorolie	Uitvoeren
8/20/25	67,336	BMW/MINI service standaard omvang	Uitvoeren
8/20/25	67,336	controle niveaus	Uitvoeren
8/20/25	67,336	klein materiaal	
8/20/25	67,336	remblokken achter	Vervangen
8/20/25	67,336	remvloeistof	Vervangen
4/25/25	57,967	BMW/MINI service standaard omvang	Uitvoeren
4/25/25	57,967	BMW/MINI voertuigcontrole	Uitvoeren
4/25/25	57,967	bougie	Vervangen
4/25/25	57,967	klein materiaal	
4/25/25	57,967	remblokken vooraan	Vervangen
4/25/25	57,967	service luchtfilter	Uitvoeren
4/25/25	57,967	service microfilter	Uitvoeren
4/25/25	57,967	service motorolie	Uitvoeren
8/30/24	43,572	batterij	Vervangen
8/30/24	43,572	BMW/MINI service standaard omvang	Uitvoeren
8/30/24	43,572	remblokken achter	Vervangen
5/17/24	34,011	BMW/MINI service standaard omvang	Uitvoeren
5/17/24	34,011	BMW/MINI voertuigcontrole	Uitvoeren
5/17/24	34,011	service microfilter	Uitvoeren
5/17/24	34,011	service motorolie	Uitvoeren