Audi

AUDI E-TRON SPORTBACK (GEA)(11.2019->) 55 QUATTRO ADVANCED MOTEUR ÉLECTRIQUE 300 KW (CONT. 158 KW) 4 PORTES

VIN: WAUZZZGE0NB041076



Description

Registration number 2CGY662	**First registration date** 25/07/2022	**Odometer** 126420 km
Color Noir Mythe Métallisé	**Model year** 2019	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Gearbox type Automatic	**Engine type** Electric	**Number of gears** 1
Max power 300 KW		

Vehicle Equipments

Rear-view camera	Rain-sensitive wipers	Automatic headlights
Climate control	Towing	Alloy wheel rims
Hydraulic tail board	Electrically foldable door mirrors	Cruise control
Heated door mirrors	Heated seats	Electrically adjustable seats
Park Assist	SATNAV	Sliding roof

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 23/10/2026	**Inspection approval date** 26/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

001	Rim / Front Left Rim/Tyre diameter : 21 "	Scratched	Repair





002	Rim / Front Right Rim/Tyre diameter : 21 "	Scratched	Repair






003	Rim / Back Right Rim/Tyre diameter : 21 "	Scratched	Repair





004	Rim / Back Left Rim/Tyre diameter : 21 "	Scratched	Repair





005	Lower door / Front Right	Chip	Acceptable




006	Door / Back Right [1]	Scratched	Polishing






007	Door / Front Right [2]	Scratched	Polishing

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




008	Wing extension moulding / Back Right [3] Painted : Yes	Scratched	Polishing




009	Seat / Front Right	Stained	Cleaning




[1] Les griffes ne sont pas profondes

[2] Griffes pas profondes

[3] Griffes pas profondes

Loose Items

- ☑ Slow charging cable (Type 2, Mode 2)
- ☑ Conformity certificate
- ☑ Card key
- ☑ User manual
- ☑ Quick charging cable (Type 2, Mode 3)
- ☑ Registration certificate
- ☑ Hook /Hicth ball
- ☑ Load cover
- ☑ Registration certificate owner
- ☑ Spare Key

Main set of tyres

Front Left	GOODYEAR	265/45/21 Summer	8 mm
Front Right	GOODYEAR	265/45/21 Summer	8 mm
Back Left	GOODYEAR	265/45/21 Summer	8 mm
Back Right	GOODYEAR	265/45/21 Summer	8 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened




Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation




Cable




Cable


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Vin



Other



Other


Other


Other


Other


Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Left / Scratched


Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched


Rim / Back Right / Scratched



Rim / Back Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Rim / Back Right / Scratched



Rim / Back Left / Scratched



Rim / Back Left / Scratched



Rim / Back Left / Scratched



Lower door / Front Right / Chip



Lower door / Front Right / Chip



Door / Back Right / Scratched



Door / Back Right / Scratched



Door / Back Right / Scratched



Door / Back Right / Scratched



Door / Front Right / Scratched




Door / Front Right / Scratched



Wing extension moulding / Back Right / Scratched



Wing extension moulding / Back Right / Scratched



Seat / Front Right / Stained

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Seat / Front Right / Stained

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Appendices : SOH Report



All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.