



Expertise

Protocol number: 46042979
Order No. / Reference: 26535148
Inspection date: 19 Jun 2026

Manufacturer: Volkswagen

Model: Arteon Shooting Brake 1.4 eHybrid OPF DSG R-Line

VIN: WVGZZZ3HZPE501265



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Arteon Shooting Brake 1.4 eHybrid OPF DSG R-Line	
Vehicle Identification number	WVGZZZ3HZPE501265
Mileage (Read)	111,125 km
First registration	24 Nov 2022
Number of holders	1
Next periodical technical inspection	01/2027
(Report on hand)	
Power / Engine displacement	115 kw / 1,395 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufll / 4
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Deep Black Perleffekt
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	7,200 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP822901
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / COR 00070		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,290 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/40 R19 94W	Summer tires (with run-flat tires) on Light alloy	Pirelli	4mm / 4mm
2)	245/40 R19 94W	Summer tires (with run-flat tires) on Light alloy	Pirelli	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- Electrically adjustable and heated exterior mirrors
- Hill start assist
- Chrome trim on the side windows
- Decorative inlays "Piano Black"
- Digital Cockpit Pro, multicolor
- Easy Open & Close - tailgate with sensor-controlled opening and closing, with remote unlocking
- Door sills with stainless steel inserts
- Electronic Stability Program with counter-steering support
- Chassis: Adaptive chassis control DCC including driving profile selection
- Luggage compartment cover
- Rear window heated
- Interior lights with delayed shut-off and dimming function
- ISOFIX mounting points
- Air conditioning system "Air Care Climatronic" with 3-zone temperature control and allergen filter
- Rear headrests (3)
- LED 3D taillights with dynamic turn signals
- Steering wheel: Multifunction sports steering wheel in leather, with touch controls and paddle shifters
- Fatigue detection
- Mesh partition
- Non-smoking version
- Emergency call service
- Otto particulate filter
- Brushed stainless steel pedals
- Wheel locks with enhanced theft protection
- Tire pressure monitoring system (passive)
- Automatically heated front windshield washer nozzles
- Side trim strips at the bottom in chrome
- Seat belts:
- Seats: Rear bench seat undivided, backrest asymmetrically split and foldable
- Seats: Heated front seats
- Seat center panels of the front seats and the outer rear seats in microfleece "ArtVelours"
- Start-stop system
- Front bumper in "R" styling
- Textile floor mats front and rear
- First aid kit, warning triangle and high-visibility vest
- Prepared for "We Connect" and "We Connect Plus"
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Adaptive Cruise Control (ACC) "stop & go", including speed limiter
- Third brake light
- Roof headliner in titanium black
- Decorative inlays in aluminum "Silver Rise"
- Dual-tone signal horn
- Parking aid - warning signals for obstacles in the front and rear area
- Electronic parking brake including auto-hold function
- Driving profile selection
- Electric windows, front and rear
- Pedestrian detection and active hood
- Transmission: 6-speed DSG
- Rear window wiper
- Interior mirror, automatically dimming
- Cable for AC charging station
- Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer
- Front headrests
- LED headlights with daytime running lights
- Dynamic headlight range control
- Front center armrest with storage box
- Navigation system "Discover Media" incl. "Streaming & Internet"
- Emergency braking assistant "Front Assist" (for automatic distance control ACC up to 210 km/h)
- Package: Light and Visibility
- Progressive steering
- Rain sensor
- Gearshift knob in leather
- Keyless locking and starting system "Keyless Access" without safe locking
- Seats: Lumbar support in the front, electrically adjustable on the driver's side
- Seats: Top comfort seats in the front
- Seats: Height-adjustable front seats, ergoComfort seat on the driver's side
- Lane keeping assistant "Lane Assist"
- 12V power outlet on the rear of the center console
- Daytime running lights with cornering lights
- USB-C interface
- Traffic sign recognition
- Warning tone and light for unfastened seat belts front and rear
- Central locking with remote control



Extra equipment

- Electronic differential lock XDS
- Package: Acoustic package (noise-reducing laminated safety glass for front side windows; rear and rear side windows tinted)
- Package: Ambient lighting (30-color ambient lighting - LED entry/warning lights in the front doors)
- Package: Business Premium (230V socket on the rear center console - "Travel Assist", "Lane Assist" and "Emergency Assist" driving assistants - "Air Care Climatronic" air conditioning with active combination filter, rear controls and 3-zone temperature control - front lumbar support, electrically adjustable on the driver's side, massage function on the driver's side - USB-C interface and USB charging socket; charging power up to 45W - heated front seats and outer rear seats)
- Paint finish: Pearl effect
- Towbar, foldable (with electric release)
- Wheels: Alloy (4) Montevideo 8 J x 19, in black/gloss-turned, Volkswagen R (AirStop tires 245/40 R 19)
- Navigation system "Discover Pro" incl. "Streaming & Internet" (23.4 cm screen diagonal with touchscreen - App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Digital radio reception DAB+ - Navigation system "Discover Pro" - Map with 2D display - Voice control - Telephone interface "Comfort" with inductive charging function - Traffic sign recognition - Preparation for mobile key, for vehicle access via smartphone - USB-C)
- Package: Driver Assistance Package (excluding "Side Assist") in conjunction with Business Premium Package (cornering and bad weather lights - Dynamic Light Assist high beam control - LED headlights with LED daytime running lights and cornering lights - Dynamic headlight range control with dynamic cornering lights - Travel Assist, Lane Assist and Emergency Assist - Park Assist including parking aid - Rear View camera)
- Surround view "Area View" including reversing camera "Rear View" (displays the vehicle's surroundings in real time on the radio/navigation system display - assists when exiting blind driveways or side streets, when parking in and out of parking spaces, when maneuvering with a trailer or when driving off-road)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear left side	Door - dent(s) - Smooth repair work
2	Front bumper	Front bumper - Scratched - Smart repair
3	Rear bumper	Rear bumper - Scratch(es) - Paint
4	Vehicle glazing	Windscreen (Rissbildung) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.






Figure 29: Misc.




Damage 1: Door - rear left side: Door - dent(s) - Smooth repair work



Damage 1: Door - rear left side: Door - dent(s) - Smooth repair work




Damage 2: Front bumper: Front bumper - Scratched - Smart repair



Damage 2: Front bumper: Front bumper - Scratched - Smart repair



Damage 2: Front bumper: Front bumper - Scratched - Smart repair



Damage 2: Front bumper: Front bumper - Scratched - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 4: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 4: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace