



## Fiat Talento: 2ALN686

|                                     |                                 |                         |              |
|-------------------------------------|---------------------------------|-------------------------|--------------|
| Vinnumber:                          | <b>ZFAFFL006M5151886</b>        | Versionname:            |              |
| First Registrationdate:             | <b>4/05/2021</b>                | Fiscalpower:            |              |
| Expertise Mileage:                  | <b>231417</b>                   | Power Kw:               |              |
| Bodytype:                           |                                 | Body colour:            | <b>White</b> |
| Gearbox:                            | <b>MAN 6 VIT</b>                | Type of rims (mounted): | <b>Steel</b> |
| Transmission:                       | <b>Front</b>                    |                         |              |
| Fueltype:                           | <b>Diesel</b>                   |                         |              |
| Maintenance:                        | <b>OK</b>                       |                         |              |
| Maintenance:                        | <b>in 28900 km</b>              |                         |              |
| Number of doors:                    | <b>5</b>                        |                         |              |
| Number of seats:                    | <b>3</b>                        |                         |              |
| Number head rests:                  | <b>2</b>                        |                         |              |
| Type of rims (mounted):             | <b>Steel</b>                    |                         |              |
| Certificate of Conformity:          | <b>Yes</b>                      |                         |              |
| Category:                           | <b>Light Commercial Vehicle</b> |                         |              |
| Registration Certificate Car (BE):  | <b>Yes</b>                      |                         |              |
| Registration Certificate Home (BE): | <b>No</b>                       |                         |              |

## Options

|                                 |                               |                          |  |
|---------------------------------|-------------------------------|--------------------------|--|
| Number of keys total:           | <b>2</b>                      | Central consol F:        |  |
| Number keys remote:             | <b>2</b>                      | Rear parking sensors:    |  |
| Windows electric F:             |                               | Sliding door right-side: |  |
| Board Computer:                 |                               |                          |  |
| Cruise Control:                 |                               |                          |  |
| Steering wheel multifunctional: |                               |                          |  |
| Type of headlighting:           | <b>Headlighting Halogen</b>   |                          |  |
| Type of GPS:                    | <b>GPS big screen color</b>   |                          |  |
| Type of Lining:                 | <b>Lining fabrics</b>         |                          |  |
| Type of climate control:        | <b>Manual climate control</b> |                          |  |
| Type of radio:                  | <b>Multimedia</b>             |                          |  |
| Type of GPS storage:            | <b>HD</b>                     |                          |  |

## Tyres

| 205/65/16/105 T       |       |                          |       |                          |
|-----------------------|-------|--------------------------|-------|--------------------------|
| Summer tyres:         | Fr.L. | <b>Continental: 3 mm</b> | Fr.R. | <b>Continental: 3 mm</b> |
|                       | Re.L. | <b>Continental: 6 mm</b> | Re.R. | <b>Continental: 6 mm</b> |
| Tyre profile depth FL |       |                          |       | <b>3.0</b>               |
| Tyre profile depth FR |       |                          |       | <b>3.0</b>               |
| Tyre profile depth RL |       |                          |       | <b>6.0</b>               |
| Tyre profile depth RR |       |                          |       | <b>6.0</b>               |
| Tyre size FL          |       |                          |       | <b>205/65 R 16 105 T</b> |
| Tyre size FR          |       |                          |       | <b>205/65 R 16 105 T</b> |
| Tyre size RL          |       |                          |       | <b>205/65 R 16 105 T</b> |
| Tyre size RR          |       |                          |       | <b>205/65 R 16 105 T</b> |
| Tyre type FL          |       |                          |       | <b>Summer</b>            |
| Tyre type FR          |       |                          |       | <b>Summer</b>            |
| Tyre type RL          |       |                          |       | <b>Summer</b>            |
| Tyre type RR          |       |                          |       | <b>Summer</b>            |
| Tyre make FL          |       |                          |       | <b>256</b>               |
| Tyre make FR          |       |                          |       | <b>256</b>               |
| Tyre make RL          |       |                          |       | <b>256</b>               |
| Tyre make RR          |       |                          |       | <b>256</b>               |

## Assistance equipment

|   |            |       |            |
|---|------------|-------|------------|
| Spare wheel:                              | <b>Yes</b> | Jack: | <b>Yes</b> |
| Number of charging cables (normal):       | <b>0</b>   |       |            |
| Number of charging cables (rapid charge): | <b>0</b>   |       |            |



Armrest, Worn, Check



Steering wheel, Worn, Acceptable



Dashboard, Hole, Smart repair



Bumper F, Scratch(es), Spot repair



Bonnet, Stone chip(s), Acceptable



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Wheel aperture RR, Scratch(es), Acceptable



Wheel aperture RL, Scratch(es), Acceptable



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Acceptable



Wheel cover FR, Scratch(es), Replace



Bodywork, Not original part, Sticker removal



Aerial, Missing, Replace

