






## 2-FWF-868


2-FWF-868 · 22 June 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-FWF-868	VIN	JTNADADB10J020094
Manufacturer	TOYOTA	Transmission Type	Automatisch geschakelde Transmissie
Model	Corolla	First Admission	16-09-2024
Body Type	5 door hatchback	Odometer	61.228 <sup>km</sup>
Color	Blue	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5

# Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Left	6 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Front Right	4 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Right	6 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Spare Tire Type	Homecomer					

## Damages



Damage Part  
Frontdoor - Left

Damage Type  
Scratch(es)

Repair Type  
Replace

Acceptable  
No




Damage Part  
Reardoor - Left

Damage Type  
Scratch(es)

Repair Type  
Replace

Acceptable  
No



Damage Part  
Fender - Rear Left

Damage Type  
Small scratch(es)

Repair Type  
Touch-up / Polish

Acceptable  
No



Damage Part  
Reardoor - Left

Damage Type  
Small scratch(es)

Repair Type  
Spray

Acceptable  
No




Damage Part  
Frontdoor - Left

Damage Type  
small dents / small scratches

Repair Type  
Panelbeating & Spray

Acceptable  
No




Damage Part  
Overfender

Damage Type  
Small scratch(es)

Repair Type  
Repair

Acceptable  
No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Right Front	Damaged	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Grille	Broken	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Front	Scratch(es)	Middenstuk	Plastic Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	Scratch(es)	Spray	No



Damage Part  
Fender - Front Right

Damage Type  
Dislocated / Loose

Repair Type  
Repair

Acceptable  
No



Damage Part  
Hood

Damage Type  
Dent(s) & Scratch(es)

Repair Type  
Panelbeating & Spray

Acceptable  
No



Damage Part  
Frontdoor - Right

Damage Type  
Small scratch(es)

Repair Type  
Touch-up / Polish

Acceptable  
No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Small scratch(es)	Polish	No