



PEUGEOT 3008: GE-353-BQ

Vinnumber:	VF3M4DGZUMS265150	Versionname:	PEUGEOT 3008 1.6 HYBRID 225 E-EAT8 GT Pack VP [5P] bva 8-225CH-10cv (SUV)
First Registrationdate:	11/01/2022	Fiscalpower:	
Expertise Mileage:	43069	Power Kw:	165
Bodytype:	SUV	Body colour:	Dark Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Rear view camera	
Cruise Control		Seat cover lining	Lining Leather
Steering wheel multifunctional			Lining Alcantara
Steering wheel leather			
Seats F heated			
Type of climate control	Autom climate control		

Tyres

205/55/19/97 V				
Summer tyres:	Fr.L.	Michelin: 75%	Fr.R.	Michelin: 70%
	Re.L.	Michelin: 50%	Re.R.	Michelin: 50%
Tyre profile depth FL				3.4
Tyre profile depth FR				3.7
Tyre profile depth RL				5.0
Tyre profile depth RR				4.9
Tyre size FL				205/55 R 19 97 V
Tyre size FR				205/55 R 19 97 V
Tyre size RL				205/55 R 19 97 V
Tyre size RR				205/55 R 19 97 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RR, Tear, Replace



Tyre RL, Tear, Replace



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Charging cable (normal), Missing, Replace



Bumper corner RL, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GE-353-BQ** Date de 1ère immatriculation: **11/01/2022**
Modèle: **Peugeot 3008 1.6 HYBRID 225 E-EAT8 GT Pack VP [5P] bva 8-225CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
28/05/2024	24.510	STELLANTIS &YOU FRANCE SAS	LIQUIDE DE FREIN
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		REVISION
	0		FILTRE CLIM RPLT
25/04/2023	14.350	STELLANTIS &YOU FRANCE SAS	BALAIS ESSUIE GLACE AV AR
	0		REVISION