ARVAL
BNP PARIBAS GROUP

2AWH829

INSPECTION REPORT

End of contract

GENERAL INFO

File	323022
License plate	2AWH829
Vehicle identification number	WF02K8GY2MNA07859
Dossier	2021160101
Make	Ford Explorer 3.0i EB PHEV 457
Mileage	191351
First registration	16/08/2021
client availability date	29/09/2026
inspectionDate	05/10/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	


km/h
0
Brandstofverbruik
0
240
N
PRNDM
0 km
448 km


B
2-AWH-829
BELCAR

DAMAGES

Damages	Type	Acceptable
226	Side View Mirror Right / Shell / Replace Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
197	Door Rear Right / Trim / Replace	N
217	Door Front Right / Trim / Replace	N
35	Front Bonnet // Polish	Y
41	Windshield // Replace	Y
54	Headlight / Front left / Replace	Y
72	Side View Mirror Left // Painting	Y
106	Door Rear Left // Polish	Y
110	Wing Rear Left // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
244	Light / Front Right / Replace	Y
340	Wheel Two Tone Front Right // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
614	Front Left Door Interior Coating // Replace Completely	Y
624	Front Right Door Interior Coating // Replace Completely	Y
631	Rear Left Door Interior Coating // Repair	N
644	Rear Right Door Interior Coating // Replace Completely	Y

Damage Pictures




Bumper Rear / Lower Cover Not Painted / Replace-scratch




Rear Bonnet // Polish-scratch




Bumper Rear // Polish-scratch




Light / Rear Right / Replace-scratch




Wing Rear Right // Polish-scratch








Door Rear Right // Polish-scratch





Wheel Two Tone Front Right // Repair-scratch





Headlight / Front left / Replace-scratch




Front Bonnet // Polish-scratch

Windshield // Replace-scratch




Side View Mirror Left // Painting-scratch





Door Rear Left // Polish-scratch




Trunk Compartment / Side Cover Right / Replace-scratch






Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Right Door Interior Coating // Replace Completely-scratch






Front Right Door Interior Coating // Replace Completely-scratch





Rear Left Door Interior Coating // Repair-scratch




Front Left Door Interior Coating // Replace Completely-scratch

Wing Rear Left // Smart Repair Small-dent

Light / Front Right / Replace-cracked




Seat Front Left / Bottom Coating / Replace-worn




Side View Mirror Right / Direction Indicator / Replace-scratch




Side View Mirror Right / Shell / Replace Painted-scratch




Door Rear Right / Trim / Replace-scratch




Door Front Right / Trim / Replace-scratch