



Expertise

Protocol number: 46410403
Order No. / Reference: 26546522
Inspection date: 8 Jul 2026

Manufacturer: Mercedes-Benz
VIN: W1N4M1FB0SW381314

Model: GLB 220 d 4Matic 8G-DCT Progressive Advanced



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLB 220 d 4Matic 8G-DCT Progressive Advanced	
Vehicle Identification number	W1N4M1FB0SW381314
Mileage (Read)	168,494 km
First registration	5 Sept 2024
Number of holders	1
Next periodical technical inspection	09/2027
(Report not on hand)	
Power / Engine displacement	140 kw / 1,950 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Nachtschwarz
Doors / Seats	5 / 7
Upholstery type	Leather
Colour of upholstery	Beige



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	262 Tag(e)
Last service on / at	03/2026 at 154,111 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HD760589
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / AHW 00249		
Emission standard	EURO6;WLTP;EA;PI/CI;M, N1, N2	fine dust sticker	
Permitted total weight	2,460 kg	Empty weight	
Dimensions	4651 x 1845 x 1700		

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 100W	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	235/55 R18 100W	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 103H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/65 R17 103H	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- 4MATIC all-wheel drive
- Rear armrest
- Automatic passenger airbag deactivation
- Basic services
- On-board computer
- Roof rails in polished aluminum
- Double cup holder
- Third brake light in LED technology
- EASY-PACK tailgate
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis
- Velour floor mats
- Speed Limit Assistant
- Rear window heated
- rear window wiper
- Climate: THERMATIC automatic climate control
- Headrests (2)
- Rear headrests (3)
- Paint finish: Solid
- LED High Performance Headlights
- Steering column mechanically adjustable lengthwise and heightwise.
- Hood with power domes
- Package: Light and Visibility Package
- Package: Progressive Line Advanced
- Package: Mirror Package
- Upholstery: ARTICO leatherette/fabric
- Tire pressure monitoring system (TPMS)
- Rear view camera
- Windscreen wipers with rain sensor
- Power steering
- Seats: Rear seat backrests foldable
- Seats: Rear seat backrests foldable
- Cruise control
- Pre-installation for digital key handover
- Immobiliser
- Adaptive Highbeam Assist
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Active Lane Keeping Assist
- Anti-lock braking system (ABS)
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Chrome trim strip
- Diesel particulate filter
- Tachometer
- DYNAMIC SELECT
- ECO start/stop function
- Electronic Stability Program (ESP)
- Electric window regulators (4)
- Luggage net on driver and passenger seatbacks
- Transmission: 8G-DCT dual-clutch automatic transmission, 8-speed
- Black fabric headliner
- Communication module (LTE) for the use of Mercedes me connect services
- Fuel tank with larger volume 60 l
- Cargo area cover (roller blind)
- Steering wheel: Multifunction sports steering wheel in leather
- Mercedes-Benz emergency call system
- Navigation accessories: Extended MBUX functions
- Package: Parking package with reversing camera
- Package: Seating comfort
- Package: USB Package Plus
- Radio accessories: Digital radio
- Wheels: 45.7 cm (18") light alloy wheels in a 5-twin-spoke design
- Side panels in black grained finish with chrome insert
- Seats: 4-way lumbar support for driver and front passenger
- Seats: Comfort seats
- 12V power outlet in center console
- Front and rear underride protection
- High-visibility vest for drivers
- Decorative elements Star Pattern



Extra equipment

- Active Parking Assist (The Active Parking Assist with PARKTRONIC can not only find parking spaces - it also supports you when parking and exiting. It assists you with steering and, in vehicles with automatic transmission, also with accelerating, braking and gear changes.)
- Interior headliner fabric macchiato beige
- Package: Driving Assistance Package (Active Distance Assist DISTRONIC, active up to a speed of 160 km/h - Active Speed Limit Assist - Extended automatic restart on highways - Route-based speed adaptation - Active Steering Assist - Active Emergency Stop Assist with SOS function - Active Brake Assist - Turning function with vehicle, pedestrian and cyclist detection - Evasive Steering Assist - Active Lane Keeping Assist - Blind Spot Assist - Exit Warning Function - Pre-Safe System)
- Package: Progressive Line Advanced Plus (KEYLESS-GO Comfort Package (incl. HANDS-FREE ACCESS and KEYLESS-GO) - Ambient lighting - Wireless charging system for mobile devices in the front - Fully digital instrument display - Personalization package - Fingerprint scanner)
- Package: Winter Package (heated steering wheel - heated windshield washer system)
- Seats: Electrically adjustable driver's seat with memory function (the memory programming includes all seat adjustment options such as seat height and fore/aft position, seat cushion tilt, and backrest tilt – exterior mirrors and the optional head-up display are also integrated – dynamic seating while driving. Small movements of the seat cushion and backrest in three programs and two speeds)
- Towbar with ESP trailer stabilization
- Type designation removed from luggage compartment lid
- Upholstery: ARTICO two-tone leatherette
- Climate control: THERMOTRONIC automatic climate control (two zones with individually adjustable temperature for driver and front passenger - automatic control of temperature, air volume and air distribution (Auto button) - sensors maintain the desired climate - fine dust activated carbon filter - dew point sensor prevents window fogging and enables energy-efficient climate control - rear center vents for improved climate comfort in the rear - residual heat button for heating/ventilation when the vehicle is switched off (country-dependent))
- Package: Night (Progressive) (Exterior mirror housings painted in solid black and heat-insulating dark-tinted glass from the B-pillar onwards - Central Mercedes star and single louvre of the radiator grille in high-gloss black with chrome inlay and high-gloss black accents - Black roof rails - Front and rear underguards in high-gloss black - Belt and window line trim strips in high-gloss black - 45.7 cm (18") light-alloy wheels in 5-twin-spoke design, painted black, 235/55 R18 on 7.0J x 18 ET53)
- Panoramic sunroof
- Seats: 3rd row of seats for 2 people
- Seats: Front right seat electrically adjustable with memory function (memory programming with seat adjustment options such as height and longitudinal direction, seat cushion tilt and backrest tilt - Motion Seating with three programs and two speeds)
- Traffic Sign Assist (networked system consisting of a camera behind the windshield and navigation maps - display of speed limits, prohibitions and their cancellation in the instrument display or media display as well as in the optionally available head-up display - visual and, if desired, additional acoustic warning when exceeding the permitted maximum speed, whereby the tolerance threshold can be raised to up to 10 km/h - can recognize no-entry signs, providing a visual and acoustic warning)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - Smart repair
2	Sill - right side	Sill - Scratch(es) - Smart repair
3	Rear bumper	Spoiler - Scratch(es) - Smart repair
4	Door - rear right side	Door - dent(s) - Smooth repair work
5	Door - rear right side	Door - Scratch(es) - Paint
6	Vehicle glazing	Rear window - Scratch(es) - Replace
7	Bonnet	Bonnet - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel - Scratch(es) - No deduction
2	Door - rear left side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Comments

- Der Winterradsatz ist kein Bestandteil der Ausstattungsliste.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation




Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.





Figure 25: Misc.




Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 2: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 3: Rear bumper: Spoiler - Scratch(es) - Smart repair




Damage 3: Rear bumper: Spoiler - Scratch(es) - Smart repair




Damage 4: Door - rear right side: Door - dent(s) - Smooth repair work




Damage 4: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 5: Door - rear right side: Door - Scratch(es) - Paint




Damage 6: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 6: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 7: Bonnet: Bonnet - Stone chips - Paint




Damage 7: Bonnet: Bonnet - Stone chips - Paint




Damage 7: Bonnet: Bonnet - Stone chips - Paint



Damage 7: Bonnet: Bonnet - Stone chips - Paint



Damage 7: Bonnet: Bonnet - Stone chips - Paint



Wear and tear 2: Door - rear left side: Door - dent(s) - No deduction



Wear and tear 2: Door - rear left side: Door - dent(s) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1N4M1FB0SW381314

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ GLB 220 d 4Matic 8G-DCT
Progressive Advanced

Datum	KM-Stand	Beschreibung
25.03.2026	154.111	Regelwartungsdienst
01.12.2025	127.512	Regelwartungsdienst
18.08.2025	102.870	Bremsinspektion vo + hi; Regelwartungsdienst
21.05.2025	77.923	Regelwartungsdienst
26.02.2025	51.195	Regelwartungsdienst
19.11.2024	26.905	Regelwartungsdienst