



MERCEDES-BENZ CLASE E: 6550-MFT

Vinnumber:	W1KZF0EB8PB119256	Versionname:	Mercedes E 220 d sedán 147kW 4P automática
First Registrationdate:	28/03/2023	Fiscalpower:	
Expertise Mileage:	165001	Power Kw:	
Bodytype:	Berline	Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Hybrid		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Seats electric F L
Number keys remote	2	Seats electric F R
GPS big screen color		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunction		
Steering wheel leather		
Seats F heated		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

245/40/19/98 Y				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/40 R 19 98 Y
Tyre size FR				245/40 R 19 98 Y
Tyre size RL				245/40 R 19 98 Y
Tyre size RR				245/40 R 19 98 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes
	Interior, Dirty, Cleaning



Registration document, Missing, Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Wing RR, Scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

