

Jeep Compass 1.4 MultiAir Longitude | Cruise | Navi | Camera | Leather | PDC |

Contact Summary

License plate	ZJ-121-H	Fuel	Gasoline
VIN	3C4NJC BH5JT404651	Transmission	Manual
Brand	Jeep	Doors	5
Model	Compass	Seats	5
Model Type	1.4 MultiAir Longitude Cruise N...	Color	Gray
VAT/Margin	VAT	Interior Color	Black
Mileage	180505 Km	Interior Type	Leather
Expected mileage	180505 Km	Paint type	
Available per	Direct	NAP status	Logical

Vehicle Details

History

Manufacture year	2019
First registration	31-05-2019 (NL)
Current registration	31-05-2019 (DE)
Imported	No

Model year	01-05-2017 → 05-05-2025
Used as	Normal
Immigration good	No
Vehicle Source	Dealer

Environment

Energy label	E
CO2 emission (NEDC)	143
EU category	Euro 6

Engine & performance

Power	103 kw
Cylinders	4
Engine	1368
Drivetrain	Frontwheeldri...

Financial

BPM deductible	Yes
Gross BPM	€ 8566
Rest BPM	€ 2249

Weights

Empty weight	1405
Towing weight	1000
Wheel base	264

Remark

Features

Specific features

Front head airbag(s).	Driver's seat adjustable in height	Rear seat can be folded down in parts
Anti-whiplash headrests	Bluetooth	Following traffic warning
LED taillights	Collision warning system	Air conditioning
LED daytime running lights	Exterior mirrors electrically adjustable	Alarm class 1 (immobilizer)
Alloy wheels 17"	Exterior mirrors in body color	Anti blocking system
Front fog lights adaptive	Central locking with remote control	Anti-slip Regulation
Multimedia preparation	Cruise control	Rear armrest
Rear parking sensor	DAB	Front armrest
Passenger airbag	Roof rails	Audio installation
Lane sensor	Dipped beam automatically	Autonomous Emergency Braking
Leather steering wheel	Electronic Stability Program	Tire pressure monitoring system
Multifunction steering wheel	Hill hold function	Driver's airbag
Front side airbag(s).	Rear head airbag(s).	

Packages

Conditions

Optical issues

Scratch(es)	
Rear left screen	
Scratch(es)	
Rear left rim	
Scratch(es)	
Rear bumper	
Star	
Windshield	
Restyle dent(s)	
Left rear door	
Not available	
Roof	
Scratch(es)	
Front left rim	

Technical inspection & maintenance

Technical inspection	31-05-2027	Keys	2
Maintenance history	Incomplete	Driveable	Yes
Last date of maintenance	06-11-2025		
Odorless	Yes		

Tyres

AllSeason	Average (3/3/4/4)
-----------	-------------------

Owner history

Date	Extra info	Owner	Number Of Days
30-05-2019	Eerste toelating Datum deel IA / I	Lease	1
31-05-2019		Autobedrijf	7
07-06-2019		Autobedrijf	54
31-07-2019		Overig zakelijk	2471
06-05-2026	Laatste tenaamstelling	Importeur	50
31-05-2027	APK vervaldatum		-

Summary



Jeep Compass 1.4 MultiAir Longitude | Cruise | Navi | Camera | Leather | PDC |

Licence plate	ZJ-121-H	Technical damage	No
Mileage	180505 Km	Optical damage	Yes
Expected Mileage	180505 Km	Nr of Owners	3
Available per	25-06-2026	Used as	Normal
Transmission	Manual	BPM Reclaimable	Yes
Drivetrain	Frontwheeldrive	Catalog	Continuous
Power	103	Lot ID	12611acb-4b42-...
VAT/Margin	VAT	Date	07-07-2026
NAP status	Logical	Remark	No
Manufacture year	2019		
Imported	No		
Country of origin	NL		