



Skoda Kodiaq:

Vinnumber:	TMBJB7NS2M8060922	Versionname:	
First Registrationdate:	4/06/2021	Fiscalpower:	
Expertise Mileage:	133545	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2806
Fueltype:	Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Sun Roof electric:	
Steering wheel multifunctional:		Panoramic roof:	
Seats F heated:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	Headlighting LED	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	No Tow bar
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

235/55/18/92 H				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL:				5.0
Tyre profile depth FR:				5.0
Tyre profile depth RL:				5.0
Tyre profile depth RR:				5.0
Tyre size FL:				235/55 R 18 92 H
Tyre size FR:				235/55 R 18 92 H
Tyre size RL:				235/55 R 18 92 H
Tyre size RR:				235/55 R 18 92 H
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				2480
Tyre make FR:				2480
Tyre make RL:				2480
Tyre make RR:				2480

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	1569,40
-------------------	---------

Backrest cover FL, Damaged, Smart repair	116,69
------------------------------------------	--------



Floor covering FL, Damaged, Replace	525,24
-------------------------------------	--------



Interior, Not original part, Replace	84,63
--------------------------------------	-------



Door FL, Dent(s), Acceptable	0,00
------------------------------	------



Boot carpet, Dirty, Cleaning	29,16
------------------------------	-------



Rear window, Scratch(es), Polish	77,26
----------------------------------	-------



Wing trim FR, Scratch(es), Replace	106,00
------------------------------------	--------




Alloy rim FR polished, Scratch(es), Acceptable	0,00
------------------------------------------------	------



Door FR, Dent(s), Paintless dent repair	95,47
-----------------------------------------	-------



Door RR, Dent(s) and scratch(es), Repair and paint (complete)	534,95
---------------------------------------------------------------	--------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof, Dent(s), Acceptable

0,00

