


MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number				Code / Agency				Date accident 10/07/2026							
				Expert code		Adjuster code				Policy number				Injured person can recover the VAT							
Date assignment 10/07/2026		Date first survey 12/07/2026		Place brindisi		C/O		Repairs		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) VOLKSWAGEN T-CROSS 1.0 TSI 81kW Style								Plate GK442RL		Vin Chassis WVGZZZC1ZNY002069				First Registration 15/06/2022							
Usage status NON CONOSCIUTO		Km 97824		Tyres %		Color nero		Type of enamel PASTEL				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0		Wheelbase								Seats No. 0		Axles 0			
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations										SR		LA		VE		ME		D.M. S.C.		Costs of spare parts	
										Dif Time		Dif Time		Dif Time		Time				* (VAT excluded)	
1		5G0012619		Tyre inflation cylinder				S		S		S									
1		2GM807521BGRU		Rear bumper lower part				S		S		S									
1		2GM945702		Rear reflector				R		S		S									
1		2GM833052P		Rear door				R		M		M									
1		2GM807421GRU		Rear bumper upper part						M		M									
1		2GM831052N		Front door				R		L				L							
1		2GM833051P		Rear door				L		L		L									
1		2GM809843A		rear mudguard				L		L		L									
1		Codice Ricambio		Smacchiatura interni																	
1		Codice Ricambio		Cerchio in lega post.				R													
1		2GA857538GRU		External rear-view mirror cap				R				L									
1		Codice Ricambio		Cerchio in lega ant. - PRM				R													
1		Codice Ricambio		Cerchio in lega ant. - PRM				L													
1		Codice Ricambio		Cerchio in lega post. - PRM				L													
1		Codice Ricambio		Mod. paraurti post. - PRM																	
1		Codice Ricambio		Mod. parafrango post. - PRM				R													

New for old value (N)	Remarks Pneum. Continental 205/60 R16. Vhl sporco.
-----------------------	--

ALPHABET

Telaio WVGZZZC1ZNY002069

GK442RL

VOLKSWAGEN T-CROSS 1.0 TSI 81kW Style sports utility vehicle 110CV 5P manuale

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
28.020	13/07/23	Tagliando a 30 000 km	Tagliando a 30 000 km
43.829	20/02/24	Tagliando a 45 000 km	Tagliando a 45 000 km
56.664	24/07/24	Maintenance	Pompa Idraulica Frizione
58.612	17/09/24	Maintenance	Pasticche freni anteriori
58.612	17/09/24	Maintenance	Pasticche freni posteriori
58.612	17/09/24	Maintenance	Spazzole tergi anteriori
58.612	17/09/24	Maintenance	Spazzole tergi posteriori
58.612	17/09/24	Tagliando a 60 000 km	Tagliando a 60 000 km
73.711	23/06/25	Maintenance	Radiatore
77.274	26/08/25	Maintenance	Tubazione
87.865	15/01/26	Tagliando a 90 000 km	Tagliando a 90 000 km