Skoda

VIN: TMBJP7NX0MY072385

Estimated repair cost

205.45 EUR
TOTAL



Description

Registration number 2DBC246	**First registration date** -	**Odometer** 63057 km
Color -	**Model year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction	net cost
001	Bonnet soundproofing / -	Tear	Replace	40.45 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.20 h	-	25.45 EUR	-
Bodywork cost	**Paint cost**	**MaterialCost**	
15.00 EUR	-	-	

#	Element	Defect	Correction	net cost
002	Rim / Front Left Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Smart repair	165.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	165.00 EUR
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

#	Element	Defect	Correction	net cost
003	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

Loose Items

- [x] Load cover
- [x] Compressor tyre repair kit
- [x] Refill tyre repair kit
- [x] Registration certificate
- [x] Spare Key
- [x] Registration certificate owner
- [x] Document holder

Main set of tyres

Front Left	CONTINENTAL	205/55/17 95 V All-season	5 mm
Front Right	CONTINENTAL	205/55/17 95 V All-season	5 mm
Back Left	GOODYEAR	205/55/17 95 V All-season	5 mm
Back Right	GOODYEAR	205/55/17 95 V All-season	5 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment



Dashboard from rear seat


Front passenger compartment


Front right



Odometer



Navigation


Spare Tyre



Vin

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Bonnet soundproofing / - / Tear



Bonnet soundproofing / - / Tear



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.