MACADAM









MERCEDES-BENZ GLC: FV-368-DW

Vinnumber:	**W1N2539131V274939**	Versionname:	**MERCEDES-BENZ GLC GLC 200 d Business Line VP [5P] bva 9-163CH-9cv (SUV)**
First Registrationdate:	**17/11/2020**	Fiscalpower:	
Expertise Mileage:	**109001**	Power Kw:	**120**
Bodytype:	**Off-road**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	**Autom climate control**	Seat cover lining	**Lining Other Lining Leather**

Tyres

Summer tyres:	**235/60/18/107 W**			
	Fr.L.	**Goodyear: 50%**	Fr.R.	**Goodyear: 60%**
	Re.L.	**Continental: 95%**	Re.R.	**Continental: 95%**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**4.3**
Tyre profile depth RL	**1.7**
Tyre profile depth RR	**1.7**
Tyre size FL	**235/60 R 18 107 W**
Tyre size FR	**235/60 R 18 107 W**
Tyre size RL	**235/60 R 18 107 W**
Tyre size RR	**235/60 R 18 107 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

		Jack	**No**

Armrest F M, Tear, Replace




Inner door sill RL, Dent(s), Repair and paint (complete)




Interior, Stain, Cleaning








Tyre RL, Out of tolerance, Replace




Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)






Tyre RR, Out of tolerance, Replace




Door RL, Scratch(es), Paint




Door FL, Dent(s) and scratch(es), Repair and paint (complete)






Wing RL, Dent(s), Repair and paint (complete)




Bumper F, Scratch(es), Paint








Door RR, Scratch(es), Paint




Door FR, Scratch(es), Acceptable




Wing RR, Dent(s), Repair and paint (complete)




Bumper R, Scratch(es), Paint






Tailgate / Boot, Dent(s), Repair and paint (complete)




Jack, Missing, Repair/replace (lump sum)



ALPHABET

Historique Maintenance

Immatriculation: **FV-368-DW** Date de 1ère immatriculation: **17/11/2020**

Modèle: **Mercedes GLC GLC 200 d Business Line VP [5P] bva 9-163CH-9cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
04/01/2025	79.231	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
21/12/2024	78.849	SOCIETE DE DISTRIBUTION ET DE REPARATION AUTOMOBILE	REVISION ET CLIM
	0		RECYCLAGE
	0		ADBLUE
	0		LIQUIDE DE FREIN
21/12/2023	59.396	SOCIETE DE DISTRIBUTION ET DE REPARATION AUTOMOBILE	REVISION
	0		FILTRE A AIR RPLT
	0		BALAIS ESSUIE GLACE AV
	0		REVISION
	0		ADBLUE
	0		RECYCLAGE
17/08/2023	50.451	SOCIETE DE DISTRIBUTION ET DE REPARATION AUTOMOBILE	PLAQUETTES AR RPLT
	0		RECYCLAGE
16/08/2023	50.123	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
06/12/2022	37.075	SOCIETE DE DISTRIBUTION ET DE REPARATION AUTOMOBILE	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
	0		LIQUIDE DE FREIN
30/11/2021	16.363	SOCIETE DE DISTRIBUTION ET DE REPARATION AUTOMOBILE	RECYCLAGE
	0		REVISION
	0		ADBLUE