MACADAM









RENAULT CLIO: GG-206-QF

Vinnumber:	**VF1RJA00469640094**	Versionname:	**RENAULT CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)**
First Registrationdate:	**30/05/2022**	Fiscalpower:	
Expertise Mileage:	**56479**	Power Kw:	**66**
Bodytype:	**Berline**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Steel**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Luggage cover	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	**Lining Other**
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/55/16/87 H**			
	Fr.L.	**Hankook: 35%**	Fr.R.	**Hankook: 35%**
	Re.L.	**Hankook: 60%**	Re.R.	**Hankook: 60%**

Tyre profile depth FL	**5.9**
Tyre profile depth FR	**5.9**
Tyre profile depth RL	**4.2**
Tyre profile depth RR	**4.2**
Tyre size FL	**195/55 R 16 87 H**
Tyre size FR	**195/55 R 16 87 H**
Tyre size RL	**195/55 R 16 87 H**
Tyre size RR	**195/55 R 16 87 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Stain, Cleaning







Bumper F, Scratch(es), Paint





Bumper grille, Unclasped, Dismount/Mount




Wing FR, Dent(s), Repair and paint (complete)






Wing RR, Scratch(es), Paint




Luggage cover stopper, Missing, Replace




Bumper R, Deformed / Strained, Repair and paint (complete)







ALPHABET

Historique Maintenance

Immatriculation: **GG-206-QF** Date de 1ère immatriculation: **30/05/2022**

Modèle: **Renault CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
04/09/2026	56.416	AUTO CHALLENGE	Joint de bouchon de vidange
			Filtre à Huile
			Essuie-Glace
			Essuie - Glace Avant (Remplacement)
			Essuie-Glace
			Essuie - Glace Arrière (Remplacement)
			Diagnostic électronique (Contrôle)
			Alternateur (Remplacement)
			Climatisation Recharge
			Essai routier
			Charge batterie
			Composant de charge de batterie
			Courroie d'Accessoires
			REVISION
			BALAIS ESSUIE GLACE AV AR
			BALAIS ESSUIE GLACE AV AR
			ALTERNATEUR RPLT
			ALTERNATEUR RPLT
			RECHARGE CLIM
			ESSAI
			ALTERNATEUR RPLT
			ALTERNATEUR RPLT
			COURROIE ACCESSOIRES RPLT
			ALTERNATEUR RPLT
			Entretien - Standard
			Bougie d'allumage
			Pièce principale de moteur
			Bougie d'allumage (Remplacement)
			Filtre à Air
			Liquide Lave-Glace
			Filtre à air (Remplacement)
12/06/2026	53.123	AUTO CHALLENGE	PLAQUETTES AV RPLT

Historique Maintenance

Immatriculation: **GG-206-QF** Date de 1ère immatriculation: **30/05/2022**

Modèle: **Renault CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
			BALAIS ESSUIE GLACE AV AR
			BALAIS ESSUIE GLACE AV AR
			RECYCLAGE
06/10/2025	44.230	AUTO CHALLENGE	SERENITE
			LIQUIDE DE FREIN
			RECYCLAGE
27/09/2024	30.000	AUTO CHALLENGE	REVISION
			PLAQUETTES AV RPLT
			BALAIS ESSUIE GLACE AV
			RECYCLAGE
11/08/2023	12.931	AUTO CHALLENGE	SERENITE