MACADAM









RENAULT CLIO: GJ-301-KM

Vinnumber:	**VF1RJA00069641176**	Versionname:	**RENAULT CLIO Business RÃ©versible E-TECH 140 -21 VF [5P] 6-140CH-5cv (bi-corps VU-)**
First Registrationdate:	**14/09/2022**	Fiscalpower:	
Expertise Mileage:	**61441**	Power Kw:	**103**
Bodytype:	**Berline**	Body colour	**White**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Hybrid**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Category	**VS**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Luggage cover	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Windows electric R		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/55/16/87 V**			
	Fr.L.	**Other: 25%**	Fr.R.	**Other: 45%**
	Re.L.	**Other: 60%**	Re.R.	**Other: 30%**

Tyre profile depth FL	**6.5**
Tyre profile depth FR	**5.3**
Tyre profile depth RL	**4.3**
Tyre profile depth RR	**6.1**
Tyre size FL	**195/55 R 16 87 V**
Tyre size FR	**195/55 R 16 87 V**
Tyre size RL	**195/55 R 16 87 V**
Tyre size RR	**195/55 R 16 87 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**263**
Tyre make FR	**263**
Tyre make RL	**263**
Tyre make RR	**263**

Assistance equipment

Instrument panel cover, Crack, Replace




Roof liner, Burned, Smart repair





Seat cover FR, Stain, Cleaning




Floor mat F, Burned, Smart repair





Wheel cover RR, Broken, Replace





Wheel cover FL, Broken, Replace




Door RL, Dent(s), Repair and paint (complete)





Wing RL, Dent(s) and scratch(es), Repair and paint (complete)





Central pillar L, Scratch(es), Paint






Bumper F, Scratch(es), Paint





Door RR, Dent(s), Repair and paint (complete)








Outside rear-view mirror housing R, Scratch(es), Acceptable




Luggage cover stopper, Missing, Replace




Bumper R, Chemical polution, Paint





ALPHABET

Historique Maintenance

Immatriculation: **GJ-301-KM** Date de 1ère immatriculation: **14/09/2022**

Modèle: **Renault CLIO Business Réversible E-TECH 140 -21 VF [5P] 6-140CH-5cv (bi-corps VU-)**

Date	Kilométrage	Fournisseur	Descriptif
05/08/2026	60.830	SA GARAGE DE L AEROPORT	Essuie - Glace Avant (Remplacement)
			Pieces
			Liquide de frein
			Liquide de frein (Remplacement)
			Essai routier
			Essuie-Glace
			REVISION ET CLIM ET AIR ET CARBURANT
			LIQUIDE DE FREIN
			DIVERS VITRAGE
			Filtre à air (Remplacement)
			Filtre à Huile
			Joint de bouchon de vidange
			Filtre à Air
			Bougie d'allumage (Remplacement)
			Bougie d'allumage
			Entretien - Standard
			Filtre d'habitacle (Remplacement)
			Liquide Lave-Glace
			Filtre à Pollen
31/07/2025	29.920	ESPACE AUTOMOBILE D'AUVERGNE	REVISION
			PLAQUETTES AV RPLT
			BALAIS ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
30/08/2024	20.835	SARL GARAGE DES OEILLETS	SERENITE