MACADAM








Ds DS7 Crossback (Segm. EX): 2CPR142

Vinnumber:	**VR1J4DGZUNY604548**	Versionname:	**DS7 Crossback E-Tense Performance Line 1.6i 225pk/cv 5p Aut.**
First Registrationdate:	**10/10/2022**	Fiscalpower:	
Expertise Mileage:	**54538**	Power Kw:	**133**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**235/50/19/103 V**			
	Fr.L.	**Michelin: 5 mm**	Fr.R.	**Michelin: 5 mm**
	Re.L.	**Michelin: 4 mm**	Re.R.	**Michelin: 4 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**235/50 R 19 103 V**
Tyre size FR	**235/50 R 19 103 V**
Tyre size RL	**235/50 R 19 103 V**
Tyre size RR	**235/50 R 19 103 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Number of charging cables (normal)	**1**
Number of charging cables (rapid charge)	**0**

Engine insulation, Damaged, Replace




Bonnet, Stone chip(s), Acceptable




Wing RL, Scratch(es), Acceptable





Door RL, Scratch(es), Acceptable





Boot lid covering R, Scratch(es), Smart repair




Bumper R, Scratch(es), Acceptable







Charging cable (fast), Missing, Check



Alloy rim FR polished, Scratch(es), Repair and paint (complete)





Door FR, Scratch(es), Acceptable




Door RR, Dent(s), Acceptable




Door RR, Dent(s), Paintless dent repair




Alloy rim RR polished, Scratch(es), Acceptable




Roof, Dent(s), Paintless dent repair




Onderhoudshistorie van: VR1J4DGZUNY604548

ALPHABET

Kenteken	2CPR142
Merk Model	Ds DS7 Crossback E-Tense Performance Line 1.6i 225pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	10/10/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/28/26	53,645	60000 km	Uitvoeren
9/28/26	53,645	oliezeef	Vervangen
10/15/25	43,554	controle niveaus	Uitvoeren
12/5/24	30,973	compleet achterlicht	Vervangen
12/5/24	30,973	luchtfilter	Vervangen
12/5/24	30,973	luchtfilter interieur	Vervangen
12/5/24	30,973	oliezeef	Vervangen
12/5/24	30,973	onderhoud 2e jaar	Uitvoeren
10/25/23	16,152	oliezeef	Vervangen
10/25/23	16,152	onderhoud 12 maand	Uitvoeren