



PEUGEOT 308 SW: GG-814-VD

Vinnumber:	VR3FCYHZLNY557242	Versionname:	PEUGEOT 308 SW BlueHdi 130 ACTIVE PACK VP
First Registrationdate:	8/06/2022	Fiscalpower:	[5P] bvm 6-130CH-7cv (break)
Expertise Mileage:	156718	Power Kw:	96
Bodytype:	Break	Body colour:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	HD	Rear parking sensors	
Windows electric F		Seat cover lining	Lining Other
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	205/55/16/91 T			
Winter tyres:	Fr.L.	Continental: 55%	Fr.R.	Continental: 60%
	Re.L.	Continental: 55%	Re.R.	Continental: 50%
Tyre profile depth FL				4.5
Tyre profile depth FR				4.3
Tyre profile depth RL				4.7
Tyre profile depth RR				4.8
Tyre size FL				205/55 R 16 91 T
Tyre size FR				205/55 R 16 91 T
Tyre size RL				205/55 R 16 91 T
Tyre size RR				205/55 R 16 91 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)




Tyre FR, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Bumper F, Scratch(es), Paint



Luggage compartment cover, Tear, Repair/replace (lump sum)



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: GG-814-VD Date de 1ère immatriculation: 08/06/2022

Modèle: Peugeot 308 SW BlueHDi 130 ACTIVE PACK VP [5P] bvm 6-130CH-7cv (break)

Date	Kilométrage	Fournisseur	Descriptif
04/06/2026	152.861	DEKRA AUTOMOTIVE TRAPPES	CONTROLE TECHNIQUE
17/12/2025	135.239	SARL CHRISTOPHE BURNEQUEZ	REVISION ET CLIM ET AIR ET CARBURANT
			REFUS
			BALAIS ESSUIE GLACE AV AR
			COURROIE ACCESSOIRES RPLT
			DIVERS CLIM
01/09/2025	124.300	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
22/05/2025	109.674	SARL CHRISTOPHE BURNEQUEZ	REVISION
22/11/2024	87.394	SARL CHRISTOPHE BURNEQUEZ	BALAIS ESSUIE GLACE AV AR
			REVISION ET CLIM
			LIQUIDE DE FREIN
06/11/2023	62.731	SONALP SA	PLAQUETTES AV RPLT
			FILTRE CLIM RPLT
			REVISION
			FILTRE A AIR RPLT
			REVISION
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
23/02/2023	30.767	SONALP SA	RECYCLAGE
			ADBLUE
			FILTRE CLIM RPLT
			REVISION