ARVAL
BNP PARIBAS GROUP

1UAE916

INSPECTION REPORT

End of contract

GENERAL INFO

File	323036
License plate	1UAE916
Vehicle identification number	WDD1179121N634737
Dossier	2017 327 190
Make	Mercedes CLA SB 180 d
Mileage	111340
First registration	12/03/2018
client availability date	01/10/2026
inspectionDate	06/10/2026











CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




1-UAE-916
BELCAR

DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
310	Wheel Two Tone Front Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures





Wheel Two Tone Front Right // Repair-scratch






Door Front Left // Smart Repair Small-scratch




Wheel Two Tone Front Left // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch