



RENAULT CLIO: GD-002-KY

Vinnumber:	VF1RJA00867890949	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)
First Registrationdate:	8/12/2021	Fiscalpower:	
Expertise Mileage:	99888	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Anthracite
Fueltype:	Hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Anthracite
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/55/16/87 H			
Summer tyres:	Fr.L.	Kleber: 70%	Fr.R.	Kleber: 90%
	Re.L.	Uniroyal: 45%	Re.R.	Uniroyal: 95%
Tyre profile depth FL				3.6
Tyre profile depth FR				2.2
Tyre profile depth RL				5.2
Tyre profile depth RR				1.8
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2479
Tyre make FR				2479
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Malfunction indicator, Blinking, Check



Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Stain, Cleaning



Door panel RL, Scratch(es), Acceptable



Tyre FL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Wheel cover FR, Missing, Replace



Steel rim FR, Deformed / Strained, Replace



Outside rear-view mirror housing L, Scratch(es), Polish



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Bonnet, Scratch(es), Acceptable



Wing RR, Dent(s), Repair and paint (complete)



Outer sill R, Dent(s), Repair and paint (complete)



Door trim FR, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Acceptable



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Luggage compartment cover, Missing, Replace



Rear roof pillar covering L, Scratch(es), Replace



Rear roof pillar covering R, Broken, Replace



Boot lid covering R, Scratch(es), Replace



Bumper R, Deformed / Strained, Replace and paint



Bodywork, Not original part, Sticker removal small



Historique Maintenance

Immatriculation: **GD-002-KY** Date de 1ère immatriculation: **08/12/2021**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
29/01/2026	91.765	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
19/06/2025	88.351	FAURIE AUTO MONTAUBAN	REVISION ET CLIM
	0		RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
02/04/2025	82.644	GAILLAC AUTO	REMPLACEMENT PNEUS ETE
	0		REMPLACEMENT PNEUS ETE
25/06/2024	54.970	FAURIE AUTO MONTAUBAN	RECYCLAGE
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		REVISION
15/05/2024	49.739	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
06/05/2024	49.739	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
08/06/2023	23.949	FAURIE AUTO MONTAUBAN	REVISION
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
23/05/2023	22.044	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE