MACADAM










## Dacia Bigster: JLK12R

| | | | |
|---|---|---|---|
| Vinnumber: | **UU1DJF01675363733** | Versionname: | **Bigster 1.8 Hybrid 115kW Journey** |
| First Registrationdate: | **24/11/2025** | Fiscalpower: | |
| Expertise Mileage: | **12988** | Power Kw: | **80** |
| Bodytype: | | Body colour | **Noir Nacre metaallak** |
| Gearbox: | **Automatic** | Paint type | **Metalic** |
| Transmission: | | Type of rims (mounted) | **Aluminium** |
| Fueltype: | **Hybrid Petrol** | Parking lot | **453** |
| Number of seats | **5** | | |
| Type of rims (mounted) | **Aluminium** | | |
| Maintenance needed | **No** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **1** | Rear parking sensors | |
| Autom climate control | | Rear view camera | |
| Radio multimedia | | | |

## Tyres

| Location | Position | Measures | Depth | Make | Type |
|---|---|---|---|---|---|
| Front | Left | 215 / 60 / 18 / 98 / H / Aluminium | 6,5 mm | Continental | Summer |
| | Right | 215 / 60 / 18 / 98 / H / Aluminium | 6,5 mm | Continental | Summer |
| Rear | Left | 215 / 60 / 18 / 98 / H / Aluminium | 7,0 mm | Continental | Summer |
| | Right | 215 / 60 / 18 / 98 / H / Aluminium | 6,9 mm | Continental | Summer |

## Assistance equipment

| | |
|---|---|
| Number of charging cables (rapid charge) | **0** |

### Ignition key, Missing, Replace

*No pictures to display*

### Wing FL, Scratch(es), Polish





### Wheel arch cover RL, Scratch(es), Replace





### Bonnet, Scratch(es), Repair and paint (complete)




# Onderhoudshistorie van: UU1DJF01675363733

ALPHABET

| | |
|---|---|
| **Kenteken** | JLK12R |
| **Merk Model** | Dacia Bigster 1.8 Hybrid 115kW Journey |
| **Brandstofsoort** | Benzine |
| **Datum deel1** | 11/24/25 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|---|---|---|
| 10/23/26 | 12,961 | Onderhoudsbeurt |