




Condition Report / Loss of Value Assessment II



Process

Your order dated

Venue of inspection

Date of inspection

Reference numbers

Vehicle information

Registration no.		Vehicle ident. no.	WAUZZZF25SN039955
Type of vehicle	Motor car - Estate	Color / finish	Black / metallic
Manufacturer	Audi	Next main inspection	12/2027
Type / sales designation	A6 Avant 50 TDI quattro advanced	Kilometres read	28,777 km
First registration date	2025-05-07	Emissions class	Euro 6
Gearbox / no. of gears	automatic / 8	Seats / doors	5 / 5
Axles / driven	2 / 2	No. of owners	unknown
Engine	Hybrid / Diesel / electric	Displacement / kW	2,967 ccm / 210 KW
Continuous power		Maximum power	
Charging plug		Battery capacity	

Vehicle information was communicated by the client and verified and supplemented on the vehicle.

Fitted wheels:					
Position	Type of tyre	Type of rim	Manufacturer	Dimensions	Thread depth
front left	summer tyre	alloy wheel	Yokohama	245/45R19 102Y	7 mm
front right	summer tyre	alloy wheel	Yokohama	245/45R19 102Y	7 mm
rear right	summer tyre	alloy wheel	Bridgestone	245/45R19 102Y	5 mm
rear left	summer tyre	alloy wheel	Bridgestone	245/45R19 102Y	5 mm
Type of spare tyre: Tire Fit					

Common / Condition	
✓ Vehicle is in running order	✗ Underbody check conducted
✗ Vehicle is registered	✓ Main key included (no: 1)
✓ Battery is functioning	Secondary key is stored centrally
✗ Service manual included	
✗ Test drive performed.	
service according to maintenance printout 2026-03-02 at km 28,705.	

Legende : ✓ Yes ✗ No ○ not verifiable ⊗ not included

Repaired previous damage	The previous damage was professionally and correctly rectified	Declaration
None identified.		

Remarks

Equipment according to VIN query

Standard equipment

airbag driver side/passenger side	airbag passenger side deactivatable
antilock braking system (ABS)	Audi connect (web-based services)
Audi connect (Emergency and Assistance System)	Audi Drive Select
exterior mirror aspherical, left	exterior mirror aspherical, right
exterior mirror vehicle colour	turn signal lights LED in exterior mirror integrated
roof rails anodised	parking aid plus front, sideways and rear, acoustic and optical with environment view
scuff rails with aluminium insert	Electronic Stability Control (ESP)
driver assistance system: brake assistant (Audi pre sense front)	driver assistance system: passenger protection system (Audi pre sense basic)
driver assistance system: lane-departure warning	driver assistance system: traffic sign detection
rear seat system (3 seats)	windshield heat protection glazing
cargo space lid electrically operated (open+close)	automatic transmission - Tiptronic (8-speed)
Shine package	liftgate opening automatic
interior equipment decorative trim inserts fine paint	Isofix mounts for child seat
head airbag system (Sideguard)	steering column (steering wheel) mech. height/longitudinal adjustment
Mild-hybrid 210 kW (engine 3,0 liter - 210 kW V6 24V TDI)	Mild-Hybrid-Technologie
center armrest front	model refinement
multi-media Interface MMI basic plus / MMI radio plus	multi-media Interface MMI Navigation
non-smoking package	progressive steering
radio reception digital (DAB)	tire repair kit
tire pressure indicator	diesel particulate filter
rear seat backrest split/folding (40:20:40)	windshield washer jets heated
rail system in cargo space	SCR system (AdBlue technology)
standard suspension	start/stop system
daytime running lights LED	jack
immobilizer (electronic)	heat protection glazing (sideways / rear)

Special features

Storage package	cargo space partition (net)
beverage holder rear	ambient lighting
trailer coupling (pivoting ball head)	Assistance package plus
Assistance package city	driver assistance system: 360 degree all-round protection (Audi pre sense 360°)
driver assistance system: passenger protection system (Audi pre sense Side Assist)	driver assistance system: intersection assistant
driver assistance system: egress alert	driver assistance system: intersection assistant rear end
driver assistance system: lane change assistant (Side Assist) incl. Audi pre sense rear	Assistance package Tour
driver assistance system: high-beam assistant	driver assistance system: adaptive cruise control system (Adaptive Cruise Control) with automatic distance control
driver assistance system: emergency assistant with automatic emergency	driver assistance system: predictive efficiency assistant

Special features

call	
driver assistance system: collision avoidance assistant	driver assistance system: cornering assistant left
driver assistance system: adaptive drive assistant	Assistance package parking with Remote park assist
driver assistance system: park assist	front camera (glass)
camera system surround view (Top View)	reversing camera
Audi Application Store and Smartphone Interface	control elements glass look, incl. extended aluminium look
Business package	exterior mirror electrically adjustable, heated + folding, with automatic dimming and Memory
exterior mirror with automatic curb-view tilting, right	adaptive windshield wiper, heated
Bluetooth hands-free system with voice recognition (Audi Phone Box)	comfort automatic air-conditioning 4-zone
seat heating front	interior mirror with automatic dimming
roof liner cloth, black	urea tank (SCR) 24 liter
head-up display	Isofix mounts for child seat at passenger seat
comfort key with sensor controlled liftgate release incl. (open+close)	fuel tank: 73 liter
steering wheel (sport/leather - 3-spokes) with multiple function and shift function	light alloy rims 8,5x19 (5-double-spoke design, Contrast gray, partially polished / burnished)
Matrix LED headlights	rear lights LED with dynamic flasher
headlight washer system (headlight washer system)	metallic paintwork
sidebag front and rear	sender for garage door opener (integrated)
seat ventilation front	seat covers/upholstery: leather / mono.pur 550 combination
seats front electrically adjustable (left with Memory)	lumbar support front, electrically adjustable
sound system DSP / Audi sound system	glazing rear darkened (privacy tinting) and door glasses front acoustic glass

Condition / damage

Front

front screen with rain sensor and frontcamera, chipping, repair (Image 18, Image 19)

rear

bumper rear panel -painted-, scratched, paint (Image 24, Image 25)

tyre, rims, wheel caps

LM wheel front right, scratched, replace (Image 20, Image 21)

LM wheel front left, scratched, depreciation (Image 26, Image 27)

LM wheel rear right, scratched, replace (Image 22, Image 23)

Inspection conditions

The inspection involved an appraisal of the exterior on the full assembled vehicle which took into account the inspection conditions at the time. No assurance of properties can be given of non-inspected areas or areas that cannot be fully inspected.

This document has an appendix with photo documentation with 27 photos.

Photo appendix




Picture 1




Picture 2

Photo appendix



Picture 3



Picture 4

Photo appendix



Picture 5



Picture 6

Photo appendix



Picture 7



Picture 8

Photo appendix



Picture 9



Picture 10

Photo appendix

Wartungsliste		Audi	
Auftrags-Nr.	Verkaufstyp	Kennzeichen	Zulassung
2026101337	4A58LA		2025-03-06
Fahrgestellnummer	MXB	Kilometerstand	Serviceintervall
WAUZZZF15ND09955	DMGA	38705	
Verkaufstyp	OKB	Modelljahr	Datum
A6 Avant 4.0 V8 210 A8	VNE	2025	02.03.2026
Inspektion mit Ölwechsel (flexibel)			
Bremsflüssigkeit: ersetzen Füllmenge 1 Liter		☒ OK	☐ nicht OK
Unbedingt "Instandhaltung genau genommen" in der aktuellen Fassung beachten!			
Änderungshistorie IGG: abrufen		☒ OK	☐ nicht OK
Fahrzeug vor der Hebebühne			
Signalhorn: Funktion prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Kombiinstrument: Kontrollleuchten prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Handschuhfach-, Innen- und Leseleuchte: Funktion prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Fahr- und Rückfahbeleuchtung, Bremsleuchten, Standlicht, Kennzeichenbeleuchtung, Blink- und Warnblinkanlage: Funktion prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Scheibenwaschanlage: Spritzbild prüfen und bei Bedarf einstellen	☐ OK	☒ nicht OK	☐ nicht anwendbar
Scheinwerferreinigungsanlage: Funktion prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Scheibenwischerblätter: auf Beschädigungen prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Scheinwerfer: auf Verstellung prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Innenraumfilter: ersetzen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Sicherheitsgurte: Fixierung Gurtsitze, Gurtschloss und Blockierverhalten Aufrollautomaten prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Karosserie: Fahrzeuglack bei geöffneten Klappen und Türen und Fahrzeug von unten auf Beschädigungen und Korrosion prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Wardreifeck: Vorhandensein prüfen	☒ OK	☐ nicht OK	☐ nicht anwendbar
Verbandtasche: Ablaufdatum prüfen und eintragen (10.2028) (MM/JJJJ)	☒ OK	☐ nicht OK	☐ nicht anwendbar
Reifenreparatur-Set: Vollständigkeit prüfen, Ablaufdatum prüfen und eintragen (04.2030) (MM/JJJJ)	☒ OK	☐ nicht OK	☐ nicht anwendbar

Picture 11



Picture 12

Photo appendix




Picture 13



Picture 14

Photo appendix



Picture 15




Picture 16

Photo appendix




Picture 17



Picture 18 front screen, with rain sensor and frontcamera, chipping, repair

Photo appendix



Picture 19 front screen, with rain sensor and frontcamera, chipping, repair



Picture 20 LM wheel, front right, scratched, replace

Photo appendix



Picture 21 LM wheel, front right, scratched, replace




Picture 22 LM wheel, rear right, scratched, replace

Photo appendix




Picture 23 LM wheel, rear right, scratched, replace



Picture 24 bumper rear, panel -painted-, scratched, paint

Photo appendix



Picture 25 bumper rear, panel -painted-, scratched, paint



Picture 26 LM wheel, front left, scratched, depreciation

Photo appendix



Picture 27 LM wheel, front left, scratched, depreciation