



PEUGEOT 308 SW:

Vinnumber:	VF3LCYHZKMS091284	Versionname:	1.5 BlueHDi 130 S&S EAT8 Business
First Registrationdate:	13/04/2021	Fiscalpower:	
Expertise Mileage:	140203	Power Kw:	96
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1415
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

205/55/16/91 H				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1388,42
Bumper F, Scratch(es), Repair and paint (complete)	296,58



Grille, Broken, Replace 261,17



Bonnet, Dent(s), Acceptable 0,00



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03




Wing FL, Dent(s) and scratch(es), Repair and paint (complete) 0,00




Door FL, Dent(s) and scratch(es), Repair and paint (complete) 0,00



Door RL, Dent(s), Spot repair 0,00



Wing RL, Scratch(es), Repair and paint (complete) 431,58



Outer sill L, Dent(s), Paintless dent repair 0,00



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim RR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Bodywork, Not original part, Remove lettering	0,00
---	------

