MACADAM










Peugeot 208: N484JG

Vinnumber:	**VR3UHZKXZMT095501**	Versionname:	**e-208 50kWh 100kW GT automaat**
First Registrationdate:	**29/10/2021**	Fiscalpower:	
Expertise Mileage:	**94717**	Power Kw:	**100**
Bodytype:		Body colour	**Noir Perla Nera metaallak**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**1031**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Lining semi-leather	
GPS		Panoramic roof	
Autom climate control		Rear parking sensors	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 45 / 17 / 88 / W / Aluminium	3,8 mm	Bridgestone	Summer
	Right	205 / 45 / 17 / 88 / W / Aluminium	3,8 mm	Bridgestone	Summer
Rear	Left	205 / 45 / 17 / 88 / W / Aluminium	4,6 mm	Bridgestone	Summer
	Right	205 / 45 / 17 / 88 / V / Aluminium	6,8 mm	Continental	Summer


Assistance equipment

Number of charging cables (rapid charge)	**1**

Service, Maintenance, Execute



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)









Wing RL, Scratch(es), Repair and paint (complete)




Wing FL, Stone chip(s), Repair and paint (complete)




Bumper F, Crack, Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Repair and paint (complete)





Outside rear-view mirror housing R, Scratch(es), Replace and paint





Wheel arch cover FR, Scratch(es), Replace




Boot lid covering R, Scratch(es), Replace






Bumper R, Scratch(es), Repair and paint (complete)








Bumper RM, Deformed / Strained, Replace and paint





Roof, Scratch(es), Repair and paint (complete)




Onderhoudshistorie van: VR3UHZKXZMT095501

ALPHABET

Kenteken	N484JG
Merk Model	Peugeot e-208 50kWh 100kW GT automaat
Brandstofsoort	Elektrisch
Datum deel1	10/29/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
3/7/26	87,097	Reparatie band(en)
4/16/25	72,783	Tractiebatterij lader
3/10/25	0	Accu
7/18/24	53,152	Onderhoudsbeurt
7/18/24	53,152	Vervanging band
10/11/23	31,650	Onderhoudsbeurt
10/11/23	31,650	Remvloeistof
10/3/22	13,427	Onderhoudsbeurt