MACADAM









OPEL GRANDLAND: GV-436-DB

Vinnumber:	**W0VZRHNS6P6060223**	Versionname:	**OPEL GRANDLAND 1.2 Turbo 130 ch Automatique GS VP [5P] bva 8-131CH-7cv (SUV)**
First Registrationdate:	**14/02/2024**	Fiscalpower:	
Expertise Mileage:	**149014**	Power Kw:	**96**
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Tow bar	
Number keys remote	**2**	Radio	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Type of climate control	**Autom climate control**	Rear view camera	
		Seat cover lining	**Lining Other Lining Leather**

Tyres

Summer tyres:	**225/55/18/102 W**			
	Fr.L.	**Hankook: 60%**	Fr.R.	**Hankook: 60%**
	Re.L.	**Hankook: 60%**	Re.R.	**Hankook: 60%**

Tyre profile depth FL	**4.4**
Tyre profile depth FR	**4.3**
Tyre profile depth RL	**4.3**
Tyre profile depth RR	**4.2**
Tyre size FL	**225/55 R 18 102 W**
Tyre size FR	**225/55 R 18 102 W**
Tyre size RL	**225/55 R 18 102 W**
Tyre size RR	**225/55 R 18 102 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Seat cover FR, Stain, Cleaning




Seat cover FL, Stain, Cleaning




Door panel RR, Scratch(es), Replace




Alloy rim RR, Scratch(es), Repair/replace (lump sum)






Bumper moulding FR, Scratch(es), Paint




Bumper F, Scratch(es), Paint




Bonnet, Stone chip(s), Paint




Bumper R, Scratch(es), Polish




ALPHABET

Historique Maintenance

Immatriculation: **GV-436-DB** Date de 1ère immatriculation: **14/02/2024**

Modèle: **Opel GRANDLAND 1.2 Turbo 130 ch Automatique GS VP [5P] bva 8-131CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
08/09/2026	139.638	SARL GARAGE LEPY	LIQUIDE DE FREIN
			Huile
			Main D'œuvre
			Pieces
			Main D'œuvre
			Pieces
			REVISION
23/04/2026	120.558	FIRST DISTRIBUTION NEGOCE	REVISION ET CLIM ET AIR ET BOUGIES
22/03/2026	117.677	PROFIL PLUS	REMPLACEMENT PNEUS ETE
			REMPLACEMENT PNEUS ETE
04/12/2025	101.300	EUROPE AUTOMOBILE	PLAQUETTES AR RPLT
			DISQUES PLAQUETTES AV RPLT
28/11/2025	100.824	EUROPE AUTOMOBILE	REFUS
			COURROIE DISTRIBUTION RPLT
			COURROIE ACCESSOIRES RPLT
			REVISION ET CLIM
			BALAI ESSUIE GLACE AR
26/11/2025	100.447	PROFIL PLUS	REMPLACEMENT PNEUS HIVER
25/07/2025	80.340	EUROPE AUTOMOBILE	REVISION ET CLIM ET AIR ET BOUGIES
19/03/2025	60.431	EUROPE AUTOMOBILE	LIQUIDE DE FREIN
			REVISION ET CLIM
			BALAIS ESSUIE GLACE AV
04/11/2024	40.099	PROFIL PLUS	REMPLACEMENT PNEUS HIVER
31/10/2024	39.934	EUROPE AUTOMOBILE	REVISION ET CLIM ET AIR ET BOUGIES
12/07/2024	19.783	EUROPE AUTOMOBILE	REVISION