

Renault Trucks Master:

Vinnumber:	VF6VF000568211735	Versionname:	Master RT 3T5 2.3 dCi 110kW FWD L3H1 Red Edition Plancher automatisch
First Registrationdate:	1/07/2022	Fiscalpower:	
Expertise Mileage:	196542	Power Kw:	110
Bodytype:		Body colour:	Gris Kempenners
Gearbox:	Automatic	Paint type:	Opaque
Transmission:		Type of rims (mounted):	Steel
Fueltype:	Diesel	Parking lot:	1226
Number of seats:	2		
Type of rims (mounted):	Steel		
Maintenance needed:	No		

Options

Number of keys total	1	Rear parking sensors
Manual climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 65 / 16 / 112 / R / Steel	6,5 mm	Bridgestone	All season
	Right	225 / 65 / 16 / 112 / R / Steel	7,0 mm	Bridgestone	All season
Rear	Left	225 / 65 / 16 / 112 / R / Steel	7,8 mm	Bridgestone	All season
	Right	225 / 65 / 16 / 112 / R / Steel	7,5 mm	Bridgestone	All season

Assistance equipment

Ignition key, Missing, Replace

No pictures to display

Seat cover FL, Worn, Replace



Registration document, Missing, Replace

No pictures to display

User's manual, Missing, Replace

No pictures to display

Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Wheel cover RL, Missing, Replace




Outside rear-view mirror housing L, Scratch(es), Replace



Bonnet, Bad repair, Repair and paint (complete)




Windscreen, Stone chip(s), Windscreen repair



Side wall RR, Scratch(es), Repair and paint (complete)



Side bar R, Dent(s), Replace




Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Central pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Broken, Replace



Mirror side repeater R, Scratch(es), Replace



Wheel arch cover RR, Dent(s) and scratch(es), Replace



Boot door panel RR, Crack, Repair and paint (complete)



Bumper corner RL, Deformed / Strained, Replace

