DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VXKFCYHZ6 R1048772	Registration date	23/07/2024	Exterior Color	Unknown
Brand	OPEL	Licence Plate	WES-KW610	Odometer	20 069 km
Model	ASTRA ST 1.5 Diesel 96kW GS Auto				


Inspection Details

Arrival Date	14/08/2026	Inspection ID	7122076	Inspection date	24/08/2026
Assign Date	14/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys SLC Essen














Generic equipment

Removable element

Spare wheel kit	✓
Toolkit	✓
Load cover	✓

Technical Document


User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✓

Tyres

Barum 225/45/17 V All seasons 6.0 mm

Barum 225/45/17 V All seasons 6.0 mm





Barum 225/45/17 V All seasons 7.0 mm

Barum 225/45/17 V All seasons 7.0 mm

Exception / Damage

1



Part	Service 2	Repair Time	-	Part Cost	300.00€
Position	-	Repair Cost	-	Gross Cost	300.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**300.00€**

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2



Part	Step plate	Repair Time	-	Part Cost	-
Position	Back	Repair Cost	-	Gross Cost	105.00€
Damages	Scratched	Paint Time	0.70	Depreciation %	-
Severity	-	Paint cost	105.00€	Depreciation	-
Repair mode	Smart Repair	Flat Rate	105.00€	**Net Cost**	**105.00€**

3



Part	Engine cover	Repair Time	0.10	Part Cost	139.17€
Position	Front	Repair Cost	14.00€	Gross Cost	153.17€
Damages	Broken	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 22.98
Repair mode	Replace	Flat Rate	-	**Net Cost**	**130.19€**

4

Part	Windscreen	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

5

Part	Bonnet	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

6

Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

7



Part	Door jamb trim	Repair Time	-	Part Cost	-
Position	Front left	Repair Cost	-	Gross Cost	30.00€
Damages	Scratched	Paint Time	0.20	Depreciation %	-
Severity	-	Paint cost	30.00€	Depreciation	-
Repair mode	Polishing	Flat Rate	30.00€	**Net Cost**	**30.00€**

8

Part	Paint preparation	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	195.00€
Damages	-	Paint Time	1.30	Depreciation %	15.00%
Severity	-	Paint cost	195.00€	Depreciation	- 29.25
Repair mode	Paintworks	Flat Rate	-	**Net Cost**	**165.75€**

Summary Inspection

Gross Price	783.17€	Depreciation	-52.23€	Net Price	730.94€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	0.10	14.00€	15.00 %	-2.10€	11.90€
Paintwork	150.00€	0.90	135.00€	-	-	135.00€
Paint preparation	150.00€	1.30	195.00€	15.00 %	-29.25€	165.75€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	439.17€	4.75 %	-20.88€	418.29€
Flat Rate	-300.00€	-	-	-300.00€