



Opel Crossland:				
Vinnumber:	W0V7H9EN2M4182921	Versionname:		
First Registrationdate:	21/06/2021	Fiscalpower:		
Expertise Mileage:	159570	Power Kw:	81	
Bodytype:		Body colour	Black	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	3828	
Fueltype:	Diesel			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Luggage cover		
Cruise Control		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Seats F heated		Type of Tow bar	Tow bar removable	
Radio multimedia				
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining artificial leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	195/60/16/89 H			
	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 2 mm
Tyre profile depth FL			2.0	
Tyre profile depth FR			2.0	
Tyre profile depth RL			4.0	
Tyre profile depth RR			2.0	
Tyre size FL			195/60 R 16 89 H	
Tyre size FR			195/60 R 16 89 H	
Tyre size RL			195/60 R 16 89 H	
Tyre size RR			195/60 R 16 89 H	
Tyre type FL			Summer	
Tyre type FR			Summer	
Tyre type RL			Summer	
Tyre type RR			Summer	
Tyre make FL			255	
Tyre make FR			255	
Tyre make RL			255	
Tyre make RR			255	
Assistance equipment				
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			399,45	
Interior, Worn, Acceptable			0,00	



Bonnet, Dent(s) and scratch(es), Repair and paint (complete) 324,95



Wing RL, Dent(s), Acceptable 0,00



Wing trim RL, Scratch(es), Replace 74,50



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Acceptable 0,00



Wing RR, Dent(s), Acceptable 0,00



Wing RR, Repaired, Acceptable 0,00

