



Audi A			
Vinnu	WAUZZZGY3NA044229	Versionname:	
First Registrationdate:	21/02/2022	Fiscalpower:	
Expertise Mileage:	109863	Power Kw:	81
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	4823
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options			
Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection


Tyres

205/55/16/94 V				
Summer tyres:	Fr.L.	Goodyear: 2 mm	Fr.R.	Goodyear: 2 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				2
Tyre profile depth FR				2
Tyre profile depth RL				5
Tyre profile depth RR				5
Tyre size FL				205/55 R 16 94
Tyre size FR				205/55 R 16 94
Tyre size RL				205/55 R 16 94
Tyre size RR				205/55 R 16 94
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				25
Tyre make FR				25
Tyre make RL				25
Tyre make RR				25

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			642,62
Bumper F, Scratch(es), Repair and paint (complete)			296,58



Alloy rim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Wing RL, Scratch(es), Acceptable	0,00
----------------------------------	------



Boot cover, Broken, Replace	213,01
-----------------------------	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Outside rear-view mirror housing R, Scratch(es), Acceptable	0,00
---	------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof, Dent(s), Acceptable	0,00
---------------------------	------

