

MACDAM

Skoda Enyaq '21 BEV

Vehicle information

Make:	Skoda	License:	
Gearbox:	Automatic	Body color:	
Model:	Enyaq '21 BEV	VIN:	TMBJC7NY0NF051845
Fuel type:	Electric	Power:	150 kW
Version:	Enyaq iV80	First registration	29/06/2022
Mileage:	145889 km	N° of doors:	

Damage summary

Front	1
Left	3
Rear	2
Right	2

Commercial pictures





Batterijcertificaat

Datum van diagnose: 01/07/2026



Raadpleeg het Moba-certificaat door deze QR-code te scannen

Meer weten over: www.get-moba.com



95,58%

Status van de gezondheid (SOH)*

Skoda Enyaq 80

VIN : TMBJC7NY0NF051845

Kilometerstand : 145.889 km

*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie

 CARA



Options according to the inspector				
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser
Radio multimedia	Yes	Rear view camera	Yes	Telephone equipment
				Yes

Damages

Bumper R
 Scratch(es)
 Repair and paint (complete)
 Rear



Door FR
 Dent(s)
 Repair and paint (complete)
 Right



Door RL
 Scratch(es)
 Repair and paint (partial)
 Left



Door RR
 Dent(s) and scratch(es)
 Repair and paint (complete)
 Right




Door trim RL
Scratch(es)
Replace
Left



Tailgate / Boot
Dent(s)
Repair and paint (complete)
Rear



Windscreen
Stone chip(s)
Windscreen repair
Front



Wing RL
Deformed / Strained
Repair and paint (complete)
Left



Tyres	
	Front Left
	Summer
	255/50/19/107/T
	Pirelli
	4.7 mm
	Front Right
	Summer
	255/50/19/107/T
	Pirelli
	4.3 mm
	Rear Left
	Summer
	255/50/19/107/T
	Pirelli
	4.7 mm
	Rear Right
	Summer
	255/50/19/107/T
	Pirelli
	5.1 mm

Checks			
Certificate of Conformity	No	CO2 Emission	0
Digital maintenance	Yes	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	N/A	User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.