MACADAM








PEUGEOT 2008: 6296-LZM

Vinnumber:	**VR3UDYHSKNJ692977**	Versionname:	**Allure BlueHDI 81kW (110CV) todoterreno 81kW 5P manual**
First Registrationdate:	**29/07/2022**	Fiscalpower:	
Expertise Mileage:	**116418**	Power Kw:	
Bodytype:	**SUV**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**No**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**2**	Luggage cover	
GPS big screen color		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**215/60/17/96 H**			
	Fr.L.	**Goodyear: 6 mm**	Fr.R.	**Goodyear: 6 mm**
	Re.L.	**Goodyear: 3 mm**	Re.R.	**Goodyear: 3 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**215/60 R 17 96 H**
Tyre size FR	**215/60 R 17 96 H**
Tyre size RL	**215/60 R 17 96 H**
Tyre size RR	**215/60 R 17 96 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Boot lid covering R, Scratch(es), Replace




MOT certificate, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)




Interior, Dirty, Cleaning




Malfunction indicator, Blinking, Check




Door RL, Scratch(es), Acceptable




Door FL, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing L, Scratch(es), Acceptable




Bumper F, Scratch(es), Repair and paint (complete)





Bonnet, Scratch(es), Acceptable




Door RR, Dent(s) and scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Acceptable




Bumper corner RL, Scratch(es), Repair and paint (complete)




Bumper moulding RM, Scratch(es), Repair and paint (complete)






Tyres, No damage, Check






ALPHABET

Datos del vehículo

Marca	PEUGEOT	Matrícula	6296-LZM
Modelo	2008	VIN	VR3UDYHSKNJ692977
Versión	Allure BlueHDI 81kW (110CV) todoterreno 81kW 5P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
22/06/2023	Revisión 1 año	25858	TALLERES AUTO ISLA C.B.
05/02/2024	Alineado, Sustitución	47362	ZAMORA AUTOS, S.L.
05/03/2024	Revisión 1 año	49670	TALLERES AUTO ISLA C.B.
27/08/2024	Bateria	67455	TALLERES AUTO ISLA C.B.
05/12/2024	Rev. 75.000 kms	75220	TALLERES AUTO ISLA C.B.
07/07/2025	Disco freno dl dr, Disco freno dl iz - DELPHI - Rec.Plat. EuroTaller, Pastillas freno dl, Sustituir Juego discos-pastillas dl	90226	TALLERES AUTO ISLA C.B.
10/10/2025	Aceite motor - - - ALP EURO, Arandela / tapón cárter - GOMA, Filtro aceite, Filtro antipolen, Líquido lavaparabrisas - -20ºC - Nueva, Serv inspección 90000 KM, Sustituir Filtro antipolen, Tasa de gestión de aceites usados	95206	TALLERES AUTO ISLA C.B.
23/07/2026	Ecotasa - N2, Goodyear / 577186 215/60X17 GYEAR.EFFIC.SUV 96H, Reparación pinchazo, Sustitucion y kit de montaje	113111	ISAIAS GUERRA E HIJOS S.L.
12/08/2026	Luna parabrisas	113523	RALARSA HOLDING S.L.

Fecha	Descripción	Kilómetros	Taller