

## Skoda Superb:

Vinnumber:	<b>TMBJW7NP6M7066843</b>	Versionname:	
First Registrationdate:	<b>19/05/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>103322</b>	Power Kw:	
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1312</b>
Fueltype:	<b>Hybrid Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Number of keys total	<b>2</b>	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar collapsible</b>
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

## Tyres

215/55/17/92 H				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>215/55 R 17 92 H</b>
Tyre size FR				<b>215/55 R 17 92 H</b>
Tyre size RL				<b>215/55 R 17 92 H</b>
Tyre size RR				<b>215/55 R 17 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>256</b>
Tyre make FR				<b>256</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

## Assistance equipment

Number of charging cables (normal)	<b>2</b>		
Number of charging cables (rapid charge)	<b>1</b>		
Total cost ex VAT			<b>2231,69</b>
Bumper F, Scratch(es), Acceptable			<b>0,00</b>



Bonnet, Chemical polution, Repair and paint (complete) 487,44



Windscreen, Repaired, Acceptable 0,00



Wing RL, Dent(s) and scratch(es), Acceptable 0,00




Door RL, Scratch(es), Acceptable 0,00



Bumper R, Deformed / Strained, Replace and paint 1083,72



Tailgate / Boot, Dent(s), Acceptable 0,00



Rear window, Scratch(es), Replace 660,53



Alloy rim FR, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Acceptable 0,00

