Iveco Daily 35C14 Open box 2019

ZCFCD35A50D638217 · lot Costs



VEHICLE DATA & SPECIFICATIONS

VIN	zcfcd35a50d638217
First Registration	8/23/2019
Country of Origin	Netherlands
Mileage	159,418 km
Iveco Daily 35C14 Open box 2...	Lot: 5Veghel, NetherlandsFirst registration: August 23, 2019Mileage: 159,418 km140 hp
Front / Right	Back / Left
Place your bid	Auto-bid
Transport costs	
Vehicle location	
Engine Output HP/PK	140 hp
Power type	Diesel
Engine Type	F1AGL411R
Emission norm	Euro 6
Cilinder Amount	4
Distribution type	Belt
Engine displacement (cc)	2287
Amount of Axles	2
Type of suspension axle 2	parabolic
Type of tyres axle 2	Double
Tyre condition Axle 1 Right (M...	3 mm
Tyre condition Axle 2 Left (MM)	6 mm

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Tyre condition Axle 2 Left 2(M...	6 mm
Tyre condition Axle 2 Right (M...	6 mm
Tyre condition Axle 2 Right 2(...	6 mm
Tyre size Axle 1	195/75 R16
Tyre Size Axle 2	195/75 R16
Undercarriage	Wheeled
Wheelbase	375 cm
Tyre condition Axle 1 Left (MM)	3 mm
Empty weight	2655 kg
Registration Date	2019-08-23
Towing weight	3500 kg
NAP	Logisch
Type Lights	Halogen
Working lights	2
Gross Vehicle Weight (GVW)	3500 kg
VIN / Serial Number/ Chassisn...	ZCFCD35A50D638217
Brand	Iveco
Model	Daily
Product Group (Tax)	Open
Axle capacity 1	1900 kg
Axle configuration	2002-10-04
Colour	orange
Country of origin	NL
Type of drive	RWD
Type extended	Daily 35C14
Inner length	409 cm
Inner width	205 cm
Headboard height	150 cm
Material floor	Wood
Sideboard height	40 cm
Superstructure brand	Ingimex
Superstructure build year	2019
Max load capacity	845 kg
Vehicle Height (cm)	235 cm
Vehicle Length (cm)	665 cm
Vehicle Width (cm)	208 cm
Mileage	159418 km
Airco option	airco
Number of seats	2
Type of cabin	Single
Type of Radio	FM

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Type of Tacho	Digital
Tail lift capacity	500 kg
Plateau length	235 cm
Tail lift brand	DEL
Tail lift build year	2019
Tail lift type	DL500FG
Type of taillift	Taillift
Amount of forward gears	6
Transmission	Manual
Truck ID	70342566
Lot	5
First registration	August 23, 2019
November 10, 2026 at 02	02 PM

Damage & Condition

All known damages are listed and shown in photos for full transparency.

1 damage reported | Worst: Minor



Windshield
Cosmetic Damage
Condition windshield

Minor



Front / Right



Back / Left




IVECO










IVECO


1.zij contr.
100%
742