



BMW 1:

Vinnumber:	WBA7K310607J61501	Versionname:	
First Registrationdate:	14/06/2021	Fiscalpower:	
Expertise Mileage:	86230	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3115
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/45/17/92 H				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	225/45 R 17 92 H			
Tyre size FR	225/45 R 17 92 H			
Tyre size RL	225/45 R 17 92 H			
Tyre size RR	225/45 R 17 92 H			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	259			
Tyre make FR	259			
Tyre make RL	259			
Tyre make RR	259			

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1678,04
Wing RL, Dent(s) and scratch(es), Repair and paint (complete)	491,09



Door RL, Scratch(es), Acceptable		0,00
		
Alloy rim RL polished, Scratch(es), Acceptable		0,00
		
Alloy rim FL polished, Scratch(es), Repair and paint (complete)		204,21
		
Bumper R, Scratch(es), Repair and paint (complete)		356,09
		
Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)		422,44
		
Alloy rim FR polished, Scratch(es), Repair and paint (complete)		204,21
		