



Hyundai Tucson:

Vinnumber:	TMAJD81BANJ175452	Versionname:	
First Registrationdate:	12/09/2022	Fiscalpower:	
Expertise Mileage:	167361	Power Kw:	110
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2102
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/65/17/92 H				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/65 R 17 92 H
Tyre size FR				225/65 R 17 92 H
Tyre size RL				225/65 R 17 92 H
Tyre size RR				225/65 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	572,67
Seat cover FL, Stain, Cleaning	29,16



Seat cover FL, Damaged, Acceptable 0,00



Seat cover FR, Stain, Cleaning 29,16



Bumper moulding F, Bad repair, Check 0,00



Bonnet, Scratch(es), Acceptable 0,00



Door RL, Dent(s), Acceptable 0,00



Step L, Dent(s) and scratch(es), Repair and paint (complete) 161,81



Alloy rim RL polished, Rust, Acceptable 0,00



Door RL, Chemical pollution, Acceptable 0,00



Door FL, Dent(s) and scratch(es), Spot repair 148,33



Rear window, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Acceptable 0,00



Door FR, Dent(s), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21



Step R, Scratch(es), Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00

