



Peugeot 2008: L21LR

Vinnumber:	VR3UKZKXZMJ551854	Versionname:	e-2008 100kW/ 50kWh GT Pack
First Registrationdate:	3/07/2021	Fiscalpower:	
Expertise Mileage:	74110	Power Kw:	100
Bodytype:		Body colour	Orange Fusion metaallak
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	741
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Panoramic roof
Radio multimedia		Rear parking sensors
		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 18 / 99 / V / Aluminium	5,8 mm	Michelin	Summer
	Right	215 / 55 / 18 / 99 / V / Aluminium	6,1 mm	Michelin	Summer
Rear	Left	215 / 55 / 18 / 99 / V / Aluminium	5,3 mm	Michelin	Summer
	Right	215 / 55 / 18 / 99 / V / Aluminium	4,3 mm	Michelin	Summer


Assistance equipment

Number of charging cables (rapid charge)	1
--	---

Interior, Stain, Cleaning



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Roof pillar L, Scratch(es), Repair and paint (complete)




Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RL, Scratch(es), Replace



Wheel arch cover RL, Scratch(es), Replace



Bonnet, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wheel arch cover RR, Scratch(es), Replace



Bumper moulding R, Scratch(es), Replace and paint



Bumper corner RR, Scratch(es), Repair and paint (complete)



Bumper corner RL, Scratch(es), Repair and paint (complete)



Bumper R, Dent(s), Replace



Rear spoiler, Chemical polution, Repair and paint (complete)



Roof, Chemical polution, Repair and paint (complete)



Kenteken	L021LR
Merk Model	Peugeot e-2008 100kW/ 50kWh GT Pack
Brandstofsoort	Elektrisch
Datum deel1	03-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
13-03-26	70.023	Airco reinigen
13-03-26	70.023	Onderhoudsbeurt
13-03-26	70.023	Sleutelbatterij
18-06-25	59.340	APK
18-06-25	59.340	Onderhoudsbeurt
18-06-25	59.340	Remvloeistof
18-06-25	59.340	Vervanging band
10-06-25	55.310	ABS pomp
10-06-25	55.310	Sensor ABS/ASR
13-05-25	57.586	Tractiebatterij lader
06-06-24	44.552	Sleutel/Kaart
07-02-24	40.728	Onderhoudsbeurt
07-02-24	40.728	Remvloeistof
20-06-23	33.141	Airo vulling
23-12-22	25.945	Controle beurt
22-09-22	20.400	Onderhoudsbeurt
17-05-22	14.612	Vervanging band
14-02-22	10.625	Onderhoudsbeurt