



MERCEDES-BENZ EQE: 6979-MHJ

Vinnumber:	W1KEG2FB5PF030131	Versionname:	Mercedes 350 sedán 215kW 4P automática
First Registrationdate:	7/06/2023	Fiscalpower:	
Expertise Mileage:	63996	Power Kw:	
Bodytype:	Berline	Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Electric		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Seats electric F L
Number keys remote	2	Seats electric F R
GPS big screen color		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Seats F heated		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	255/35/21/98 Y			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				255/35 R 21 98 Y
Tyre size FR				255/35 R 21 98 Y
Tyre size RL				285/30 R 21 100 Y
Tyre size RR				285/30 R 21 100 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes
Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bonnet, Stone chip(s), Paint



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyres, No damage, Check

