



**Ford Mustang: L979LT**

Vinnumber:	<b>WF0TK1EM3MMA15244</b>	Versionname:	<b>Mustang Mach-E 190kW/ 75,7kWh RWD automaat</b>
First Registrationdate:	<b>29/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>108208</b>	Power Kw:	<b>190</b>
Bodytype:		Body colour:	<b>Shadow Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Opaque</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>455</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Lining leather
GPS		Rear parking sensors
Autom climate control		
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 100 / V / Aluminium	4,8 mm	Bridgestone	Winter
	Right	225 / 60 / 18 / 100 / V / Aluminium	3,5 mm	Bridgestone	Winter
Rear	Left	225 / 60 / 18 / 100 / V / Aluminium	5,1 mm	Bridgestone	Winter
	Right	225 / 60 / 18 / 100 / V / Aluminium	5,5 mm	Bridgestone	Winter


**Assistance equipment**

Number of charging cables (normal)	<b>1</b>
Number of charging cables (rapid charge)	<b>1</b>

**Service, Maintenance, Execute**



**Door FL, Dent(s), Repair and paint (complete)**



**Door RL, Dent(s) and scratch(es), Repair and paint (complete)**



Wing FL, Dent(s), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Wheel arch cover FL, Dent(s), Replace



Bonnet, Hail damage, Paintless dent repair (hail)




Bumper F, Scratch(es), Repair and paint (complete)



Bumper trim F, Scratch(es), Replace



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Replace



Roof, Hail damage, Paintless dent repair (hail)



<b>Kenteken</b>	L979LT
<b>Merk Model</b>	Ford Mustang Mach-E 198kW/ 75,7kWh RWD automatisch
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	29-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
12-01-26	98.836	Onderhoudsbeurt
12-01-26	98.836	Remvloeistof
12-01-26	98.836	Ruitenwischerblad(en) voorzijde
12-01-26	98.836	Sleutelbatterij
12-01-26	98.836	Vervanging band
26-06-25	88.304	APK
26-06-25	88.304	High Voltage lader aansluiting
26-06-25	88.304	Ruitenwischerblad(en) achterzijde
23-09-24	72.740	Reparatie band(en)
05-12-23	49.289	Onderhoudsbeurt
05-12-23	49.289	Sleutelbatterij
05-12-23	49.289	Vervanging band
15-07-21	150	Vervanging band