Technician
Rutger Koogh

2-FMQ-690

2-FMQ-690 · COMBI L2H12.0dCi 150 DCT N-CONNECTA · 27 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FMQ-690
Manufacturer	NISSAN
Model	Primastar
Model Versions	COMBI L2H12.0dCi 150 DCT N-CONNECTA
Body Type	VAN
Color	Black
Paint Type	Metallic
Production Year	2024
KW	110

Fuel Type	Diesel
VIN	VNVJ4000X73222265
Cylinder Capacity	1.998 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	13-06-2024
Odometer	77.636 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	9

Images

































Accessories

ABS	Fog lights
Airbags	Leather steering wheel
Audio System	Manual air conditioning
Bluetooth car kit	Navigation system
Central door locking	Rear parking sensors
Centre armrest	Rear view camera
Cruise control	Roller cover / parcel shelf
Electric windows front	Steering wheel multifunction
Electrically adjustable exterior mirrors	Tow bar

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Rear Left	4 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Front Right	3 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Rear Right	4 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Spare Tire Type	Fully Fledged					
Spare Tire Profile	8 mm					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small scratch(es)	Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Mirror - Rightside	Broken	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Small scratch(es)	Polish	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Scratch(es)	B stijl	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Dent(s)	Replace	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Small scratch(es)	Achterstijl	Repair	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Small scratch(es)	Achterstijl	Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Roof	Dent(s)	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Co drivers seat	Dislocated / Loose	Bekleding	Cloth Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No