



Seat Ateca (UKL): 2CMT299

Vinnumber:	VSSZZZ5FZN6536710	Versionname:	Ateca Move! 1.0TSi 110pk/cv 5p
First Registrationdate:	20/09/2022	Fiscalpower:	
Expertise Mileage:	79519	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	over 1700 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres


215/55/17/94 V				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/55 R 17 94 V
Tyre size FR				215/55 R 17 94 V
Tyre size RL				215/55 R 17 94 V
Tyre size RR				215/55 R 17 94 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Windscreen, Repaired, Acceptable			



Windscreen, Stone chip(s), Acceptable



Bumper F, Stone chip(s), Acceptable



Wing RL, Scratch(es), Acceptable



Tyre FL, Tear, Replace



Bumper R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Acceptable





Step R, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Acceptable



Bodywork, Not original part, Remove lettering



Kenteken	2CMT299
Merk Model	Seat Ateca Move! 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	9/20/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/30/25	57,378	0139-Aanvulling op onderhoudsbeurt	Uitvoeren
7/30/25	57,378	Inspectie met olie vervanging (vast in	Uitvoeren
7/30/25	57,378	klein materiaal	
7/30/25	57,378	remvloeistof	Bijvullen/-laden
5/9/25	52,070	klein materiaal	
5/9/25	52,070	ruitenswisserrubber achter	Vervangen
5/9/25	52,070	ruitenswisserrubber vooraan	Vervangen
5/7/24	32,641	batterij	Vervangen
5/7/24	32,641	klein materiaal	Uitvoeren
5/7/24	32,641	luchtfilter interieur	Vervangen
5/7/24	32,641	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
5/7/24	32,641	ruitenswisserrubber achter	Vervangen
5/7/24	32,641	ruitenswisserrubber vooraan	Vervangen
8/30/23	19,095	controle niveaus	Uitvoeren