MACADAM








Peugeot 308 (UKL): 2DTN729

Vinnumber:	**VR3FRHNSTPY561032**	Versionname:	**308 SW Allure Pack 1.2 PureTech S&S 130pk/cv 5p EAT8**
First Registrationdate:	**21/06/2023**	Fiscalpower:	
Expertise Mileage:	**82360**	Power Kw:	**96**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**NOT OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar removable**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**225/45/17/94 H**			
	Fr.L.	**Goodyear: 7 mm**	Fr.R.	**Goodyear: 7 mm**
	Re.L.	**Goodyear: 7 mm**	Re.R.	**Goodyear: 7 mm**

Tyre profile depth FL	**7.0**
Tyre profile depth FR	**7.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**225/45 R 17 94 H**
Tyre size FR	**225/45 R 17 94 H**
Tyre size RL	**225/45 R 17 94 H**
Tyre size RR	**225/45 R 17 94 H**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Service, Maintenance, Check



Bumper F, Scratch(es), Acceptable






Engine insulation, Tear, Replace




Alloy rim FL, Scratch(es), Repair and paint (complete)







Bumper R, Dent(s) and scratch(es), Repair and paint (complete)




Bumper moulding R, Scratch(es), Repair and paint (complete)






Alloy rim RR, Scratch(es), Repair and paint (complete)







Alloy rim FR, Scratch(es), Acceptable




Onderhoudshistorie van: VR3FRHNSTPY561032

ALPHABET

Kenteken	2DTN729
Merk Model	Peugeot 308 SW Allure Pack 1.2 PureTech S&S 130pk/cv 5p EAT8
Brandstofsoort	Benzine
Datum deel1	6/21/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/5/25	62,243	60000 km	Uitvoeren
12/5/25	62,243	bobine	Vervangen
12/5/25	62,243	diagnose	Uitvoeren
12/5/25	62,243	luchtfilter interieur	Vervangen
12/5/25	62,243	oliezeef	Vervangen
3/28/25	40,000	40000 km	Uitvoeren
3/28/25	40,000	bougie	Vervangen
3/28/25	40,000	luchtfilter	Vervangen
3/28/25	40,000	luchtfilter interieur	Vervangen
3/28/25	40,000	oliezeef	Vervangen
3/28/25	40,000	remvloeistof	Vervangen
3/14/24	20,142	20000 km	Uitvoeren
3/14/24	20,142	luchtfilter interieur	Vervangen
3/14/24	20,142	oliezeef	Vervangen
3/14/24	20,142	trekhaak	