



PEUGEOT 208: 1YQQ371

Vinnumber:	VR3UBYHYJLT123532	Versionname:	
First Registrationdate:	6/11/2020	Fiscalpower:	
Expertise Mileage:	83999	Power Kw:	
Bodytype:		Body colour	Dark Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front		
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2
Number keys remote	2
Type of GPS	GPS base
Type of GPS storage	HD

Tyres

205/45/17/88 W				
Winter tyres:	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/45 R 17 88 W
Tyre size FR				205/45 R 17 88 W
Tyre size RL				205/45 R 17 88 W
Tyre size RR				205/45 R 17 88 W
Tyre type FL				Winter
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Damaged, Acceptable



Bumper F, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable



Alloy rim FL, Scratch(es), Repair and paint (complete)




Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, Not original part, Sticker removal

