



Volvo XC 90: [REDACTED]

Vinnumber:	YV1LFBMVDM1768676	Versionname:	
First Registrationdate:	27/05/2021	Fiscalpower:	
Expertise Mileage:	120193	Power Kw:	223
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2833
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Sun Roof electric:	
Seats F heated:		Panoramic roof:	
Radio multimedia:		Luggage cover:	
Type of headlighting:	Headlighting LED	Front parking sensors:	
Type of GPS:	GPS big screen color	Rear parking sensors:	
Type of Lining:	Lining artificial leather	Type of Tow bar:	Tow bar collapsible
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

275/35/20/92 H				
Summer tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				275/35 R 20 92 H
Tyre size FR				275/35 R 20 92 H
Tyre size RL				275/35 R 20 92 H
Tyre size RR				275/35 R 20 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				2484
Tyre make RR				2484

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	1		

Total cost ex VAT 1438,44

Bumper F, Scratch(es), Acceptable 0,00



Alloy rim RL polished, Scratch(es), Acceptable 0,00



Step L, Scratch(es), Repair and paint (complete) 161,81



Door RL, Dent(s), Acceptable 0,00




Charging cable (normal), Missing, Check 0,00



Bumper R, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), Polish 77,26



Bumper moulding R, Dent(s), Replace 94,19



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Wing trim FR, Scratch(es), Acceptable 0,00



Door FR, Dent(s) and scratch(es), Repair and paint (complete) 534,95



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

204,21



Step R, Dent(s) and scratch(es), Repair and paint (complete)

161,81

