



VOLKSWAGEN CRAFTER: FR-485-FF

Vinnumber:	WV1ZZSYZL9029935	Versionname:	VOLKSWAGEN CRAFTER 2.0TDI 177 35 L3H3 Busi
First Registrationdate:	7/07/2020		Line Plus BVA8 VU [4P] bva 8-177CH-7cv (fourgon
Expertise Mileage:	262341		tÃ´lÃ© simple cabine)
Bodytype:	Transporter	Fiscalpower:	
Gearbox:	Automatic	Power Kw:	130
Transmission:	Front	Body colour:	White
Fueltype:	Diesel	Paint type:	Opaque
Engine functioning:	Yes	Interior colour:	Black
Battery functioning:	Yes	Type of rims (mounted):	Steel
Vehicle running:	Yes	Dashboard color:	Black
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
GPS big screen color		Rear parking sensors	
GPS storage		Sliding door right-side	
GPS storage	SD	Rear view camera	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Type of climate control	Manual climate control		

Tyres

205/75/16/113 R			
Summer tyres:	Fr.L.	Continental: 0%	Fr.R.
	Re.L.	Continental: 0%	Re.R.
Tyre profile depth FL			8.0
Tyre profile depth FR			8.0
Tyre profile depth RL			9.1
Tyre profile depth RR			8.0
Tyre size FL			205/75 R 16 113 R
Tyre size FR			205/75 R 16 113 R
Tyre size RL			205/75 R 16 113 R
Tyre size RR			205/75 R 16 113 R
Tyre type FL			All seasons
Tyre type FR			All Seasons
Tyre type RL			All seasons
Tyre type RR			All Seasons
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Spare wheel	Yes	Jack	Yes
Steering wheel, Worn, Repair/replace (lump sum)			



Seat cover FR, Burned, Replace



Seat cover FL, Hole, Replace



Floor mat F, Hole, Smart repair



Side panel L, Scratch(es), Polish



Bonnet, Stone chip(s), Paint




Outer sill R, Dent(s) and scratch(es), Replace and paint



Sliding door R, Dent(s), Repair and paint (complete)



Boot door panel RL, Dent(s), Repair and paint (complete)



Bodywork, Glue residues, Remove lettering



Historique Maintenance

Immatriculation: **FR-485-FF** Date de 1ère immatriculation: **07/07/2020**

Modèle: **Volkswagen CRAFTER 2.0TDI 177 35 L3H3 Busi Line Plus BVA8 VU [4P] bva 8-177CH-7cv (fourgon tôlésimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
18/11/2025	239.269	ESPACE UTILITAIRE 31	REVISION ET CLIM
06/10/2025	232.629	ESPACE UTILITAIRE 31	DISQUES PLAQUETTES AR RPLT
31/03/2025	210.288	ESPACE UTILITAIRE 31	REVISION
	0		KIT DISTRIBUTION RPLT
	0		KIT ACCESSOIRES RPLT
13/01/2025	198.974	ESPACE UTILITAIRE 31	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
13/12/2024	191.943	ESPACE UTILITAIRE 31	INJECTEURS RPLT
01/08/2024	181.929	ESPACE UTILITAIRE 31	DISQUES PLAQUETTES AV RPLT
30/11/2023	150.945	ESPACE UTILITAIRE 31	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
05/01/2023	110.343	ESPACE UTILITAIRE 31	REVISION ET CLIM ET AIR ET CARBURANT
	0		LIQUIDE DE FREIN
	0		PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		REVISION ET CLIM ET AIR ET CARBURANT
16/11/2022	103.802	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
	0		REMPLACEMENT PNEUS HIVER
06/07/2022	88.959	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
02/03/2022	65.090	ESPACE UTILITAIRE 31	PLAQUETTES AV RPLT
	0		REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
15/10/2021	45.436	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
25/02/2021	10.930	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		REMPLACEMENT PNEUS HIVER