

INSPECTION REPORT


End of contract

GENERAL INFO

File	314158
License plate	2DAL866
Vehicle identification number	WMW21BS0103R13022
Dossier	2022160116
Make	Mini Mini Count.Coo.S E ALL4 2
Mileage	67570
First registration	16/01/2023
client availability date	01/06/2026
inspectionDate	09/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
31	Front Bonnet // Smart Repair Small	Y
72	Side View Mirror Left // Painting	Y
86	Door Front Left // Polish	Y
95	Rocker Panel Left // Polish	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
222	Side View Mirror Right // Painting	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	Y
316	Tyre Front Left // Replace	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
568	Dashboard / Ventilation Outlet / Replace	N
840	Interior Cleaning // Large	Y

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch




Bumper Rear // Painting-scratch



Rear Bonnet // Polish-scratch



Light / Rear Right / Replace-scratch



Wing Rear Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch



Side View Mirror Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch




Wing Front right // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Polish-scratch




Door Rear Left // Polish-scratch



Rocker Panel Left // Polish-scratch



Wing Rear Left // Polish-scratch




Front Bonnet // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-dent




Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Painting-bad repair



Dashboard / Ventilation Outlet / Replace-cracked



Interior Cleaning // Large-dirty



Tyre Front Left // Replace-tear