



Renault Master:				
Vinnumber:	VF1MA000263441634	Versionname:		
First Registrationdate:	18/06/2019	Fiscalpower:		
Expertise Mileage:	178279	Power Kw:		
Bodytype:		Body colour	White	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel	
Transmission:		Parking lot	Icv03	
Fueltype:	Diesel			
Maintenance	OK			
Type of rims (mounted)	Steel			
Certificate of Conformity	Yes			
Category	Light Commercial Vehicle			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Rear parking sensors		
Radio multimedia		Type of Tow bar	Tow bar fixed	
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Type of GPS storage	HD			
Limited Technical Inspection				
Tyres				
Winter tyres:	225/65/16/110 R			
	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	BF Goodrich: 6 mm	Re.R.	BF Goodrich: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/65 R 16 110 R
Tyre size FR				225/65 R 16 110 R
Tyre size RL				225/65 R 16 110 R
Tyre size RR				225/65 R 16 110 R
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2485
Tyre make RR				2485
Assistance equipment				
Spare wheel	Yes	Jack		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				783,73
Seat cover FL, Worn, Check				0,00



Interior, Dirty, Cleaning

175,04



Interior, Worn, Acceptable

0,00



Dashboard, Hole, Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Windscreen, Stone chip(s), Windscreen repair

113,16



Wheel cover FL, Scratch(es), Replace

44,82



Mirror side repeater L, Broken, Replace

79,06



Wheel cover RL, Missing, Replace	44,82
	
Door seal FL, Broken, Replace	69,65
	
Step L, Scratch(es), Acceptable	0,00
	
Wing FL, Scratch(es), Acceptable	0,00
	
Bumper R, Dent(s) and scratch(es), Acceptable	0,00
	
Boot moulding, Scratch(es), Acceptable	0,00
	
Rear light L, Broken, Replace	167,54
	
Wheel cover RR, Missing, Replace	44,82
	
Wheel cover FR, Scratch(es), Replace	44,82
	
Bodywork, Not original part, Remove lettering	0,00

